

# Toyota VELLFIRE

standard safety equipment



## PRIMARY SAFETY

**85%**

Electronic Stability Control	<b>8.0</b> max. 8
system name	Vehicle Stability Control

Driver Monitoring System	<b>0.0</b> max. 2
system name	—

Tyre Pressure Monitoring	<b>2.0</b> max. 2
system name	TPMS

warning   
readout

Blind Spot Monitoring	<b>2.0</b> max. 2
system name	Blind Spot Monitor

    input corner mm-wave radars  
    driver side   
    passenger side

Physical Controls	<b>5.0</b> max. 6
hazard lights	

    gear   
    climate   
    music and navigation   
    turn indicators   
    windscreen wipers

## SECONDARY SAFETY

**63%**

Rear Seatbelts	<b>4.0</b> max. 4
position	outboard  centre  third row

    three-point

Rear Seatbelt Reminders	<b>2.0</b> max. 10
position	outboard  centre  third row

    visual signal   
    acoustic signal   
    occupant detection   
    passive activation

Head Protection Devices	<b>5.0</b> max. 6
position	front  rear  third row

    curtain airbag   
    centre airbag

Chest Protection Devices	<b>2.0</b> max. 3
position	front  rear

    thorax airbag

Neck Restraints	<b>4.0</b> max. 4
position	rear outboard  centre  third row

    sufficient<sup>1</sup>

Child Readiness	<b>2.0</b> max. 3
position	rear outboard  centre  front passenger  third row

    ISOFIX   
    i-Size   
    Top Tether

## COMMENTS

The Vellfire's three-star rating is disappointing for a car of this class. Unlike rivals, it lacks advanced technologies like a centre airbag, and its seatbelt reminders are incredibly basic.

primary safety	secondary safety	overall result
85%	63%	
<b>Evaluated variant:</b> VIP-Executive Lounge		
<b>Evaluated on:</b> October 31, 2025		
<b>Protocol:</b> FleetSure v1.0		

<sup>1</sup>subjective judgment