

Suzuki **IGNIS** standard safety equipment





PRIMARY SAFETY

70%

Electronic Stability Control	8.0 max. 8
system name ESP®	
Driver Monitoring System	0.0 max. 2
system name —	
Tyre Pressure Monitoring	0.0 max. 2
system name —	
warning 🔸	

system name — sensor —

readout

driver side •

passenger side 🧧

Physical Controls

6.0 max. 6

hazard lights

gear 🦸

climate

music and navigation \subset

and havigation

turn indicators

windscreen wipers •

SECONDARY SAFETY

13%

Rear Seatbelts	0.0 max. 4
position outboard centre	third row
three-point •	0
Rear Seatbelt Reminders	2.0 max. 10
position outboard cent	re third row
visual signal 🔸 🕒	0
acoustic signal • •	0
occupant detection • •	0
passive activation • •	0
Head Protection Devices	0.0 max. 6
position front rea	r third row
struck-side head airbag 🔸 🔸	0
far-side airbag 🔸 🔾	0
Chest Protection Devices	0.0 max. 3
position front re	ar
thorax airbag 🔸 🔹	
Neck Restraints	0.0 max. 4
position rear outboard centre	third row
$sufficient^1$	0
Child Pondinoss	2 0 may 3

Child Readi	ness		2.0 r	nax. 3
position	rear	rear	front	third
	outboard	centre	passenger	row
ISOFIX	•		•	0
i-Size		•	•	0
Top Tether		•	•	0

COMMENTS

The Ignis is among a handful of ageing Maruti Suzuki models that have NOT been updated with side airbags and a 3-point centre seatbelt.

primary	secondary	overall			
safety	safety	result			
70%	13%				

Evaluated variant: Sigma 1.2 MT					
Evaluated on: September 7, 2025					
Protocol: FleetSure v1.0					

 $^{^{1}\}mathrm{subjective\ judgment}$