

Toyota GLANZA standard safety equipment





PRIMARY SAFETY

70%

Electronic Stability Control	8.0 max. 8
system name ESP®	
Driver Monitoring System	0.0 max. 2
system name —	
Tyre Pressure Monitoring	0.0 max. 2
system name —	
warning 🔸	
readout 🔸	

Blind Spot Monitoring	0.0 max. 2

system name — input —

driver side • passenger side •

Physical Controls

6.0 max. 6

hazard lights

gear 🧧

climate 🧧

music and navigation \subset

turn indicators •

windscreen wipers •

SECONDARY SAFETY

63%

Rear Seatbelts				4.0 ma	x. 4
position	outboa	rd ce	ntre	third row	
three-point			•	0	
Rear Seatbelt I	Remino	lers		2.0 max	. 10
positi	on out	board	cent	re third	row
visual sigr	nal		•	0	
acoustic sigr	nal			0	
occupant detecti	on	•	•	0	
passive activati	on	•	•	0	
Head Protection	n Devi	ces		5.0 ma	x. 6
posit	ion fro	nt re	ar th	nird row	
curtain air	bag (0	
centre air	bag (0	
Chest Protection Devices 2.0 max. 3			x. 3		
	positio	n fron	t rea	ar	
thor	ax airba,	g •)	

Neck Restra	ints	4.0 max. 4		
position	rear outboard	centre	third row	
$sufficient^1$			0	

ness		2.0 r	max. 3
rear	rear	front	third
outboard	centre	passenger	row
	•	•	0
	•	•	0
		•	0
	rear		rear rear front

COMMENTS

The recently updated Glanza earns a commendable three-star rating, hurt mostly by its basic buckle-and-unbuckle type seatbelt reminders.

primary	secondary	overall	
safety	safety	result	
70%	63%		
****		***	
Evaluated variant: E 1.2 MT			
Evaluated on: October 17, 2025			
Protocol: FleetSure v1.0			

 $^{^{1}\}mathrm{subjective\ judgment}$