

Toyota GLANZA standard safety equipment





PRIMARY SAFETY

70%

Electronic Stability Control	8.0 max. 8
system name ESP®	
Driver Monitoring System	0.0 max. 2
system name —	
Tyre Pressure Monitoring	0.0 max. 2
system name —	
warning •	

Blind Spot	Monitoring	0.0	max.	2

system name sensor —

readout

driver side passenger side

Physical Controls **6.0** max. 6

hazard lights of

climate •

music and navigation \circ

turn indicators •

windscreen wipers •

SECONDARY SAFETY

63%

Rear Seatbelts			4	.0 max.	4
position out	board	centre	thi	rd row	
three-point	•	•		0	
Rear Seatbelt Rem	ninders		2.0	0 max.	10
position	outboa	rd ce	ntre	third rov	N
visual signal				0	
acoustic signal				0	
occupant detection	•		•	0	
passive activation	•		•	0	
Head Protection D)evices		5	.0 max.	6
posit	ion fr	ont re	ear t	hird row	
struck-side head air	bag	•		0	
far-side air	bag	•	0	0	
Chest Protection [Device:	5	2	.0 max.	3
pos	ition	front	rear		
thorax a	irbag		•		

Neck Restra	ints	4.0 max. 4		
position	rear outboard	centre	third row	
$sufficient^1$	•		0	

<u>Child Readi</u>	ness		2.0 r	max. 3
position	rear	rear	front	third
	outboard	centre	passenger	row
ISOFIX	•	•	•	0
i-Size		•	•	0
Top Tether			•	0

COMMENTS

The recently updated Glanza earns a commendable three-star rating, hurt mostly by its basic buckle-and-unbuckle type seatbelt reminders.

primary	secondary	overall	
safety	safety	result	
70%	63%		

Evaluated variant: E 1.2 MT			
Evaluated on: September 8, 2025			
Protocol: FleetSure v1.0			

¹subjective judgment