

Tata ALTROZ

standard safety equipment





PRIMARY SAFETY

70%

Electronic Stability Control		8.0 max. 8
system name	ESC	
Driver Monitoring System		0.0 max. 2
system name	_	
Tyre Pressure Monitoring		0.0 max. 2
system name	_	
warning		
readout		

Blind Spot Monitoring **0.0** max. 2

system name input

driver side

passenger side

Physical Controls

6.0 max. 6

hazard lights

gear

climate

music and navigation

turn indicators

windscreen wipers

SECONDARY SAFETY

passive activation

50%

Rea	r Seatbelts					4	. 0 max	<u>(. 4</u>
	position	ou	tboard	cei	ntre	thi	rd row	
	three-point						0	
Rea	r Seatbelt	Rer	ninders			2.0	O max.	10
	positi	on	outboa	ırd	cent	tre	third ro	w
	visual sigi	nal			•		0	
	acoustic sigi				•		0	
oco	cupant detecti	on	•		•		0	

Head Protection Devices			5.0 max.	6
position	front	rear	third row	
curtain airbag			0	
centre airbag	•	0	0	
Chest Protection D)evices	;	2.0 max.	3

position front rear thorax airbag

Neck Restra	ints		0.0 max. 4
position	rear outboard	centre	third row
$sufficient^1$	•	•	0

Child Read	ıness		2.0 r	<u>nax. 3</u>
position	rear outboard	rear centre	front passenger	third row
ISOFIX		•	•	0
i-Size		•	•	0
Top Tether		•	•	0

COMMENTS

The New Altroz has very poor rear seatbelt reminders, which issue an audible warning on even empty seats, without a change of belt status.

primary	secondary	overall			
safety	safety	result			
70%	50%				
****		***			
Evaluated variant: Smart 1.2 MT					
Evaluated on: October 17, 2025					
Protocol: FleetSure v1.0					

¹subjective judgment