

Hyundai **AURA** standard safety equipment





PRIMARY SAFETY

30%

		·	
Electronic Stability Control		0.0 max.	8
system name			
Driver Monitoring System		0.0 max.	2
system name	_		
Tyre Pressure Monitoring		0.0 max.	2
system name			
warning	•		
readout	•		

Blind Spot Monitoring	0.0 max. 2
-----------------------	-------------------

system name — sensor —

driver side

passenger side •

Physical Controls

6.0 max. 6

hazard lights

gear

climate of

music and navigation of

turn indicators •

windscreen wipers •

SECONDARY SAFETY

43%

Rear Seatb	elts			4.0 n	nax. 4
posit	ion out	board ce	entre	third ro	w
three-po	oin t	•		0	
Rear Seatb	elt Rem	ninders		2.0 m	ax. 10
р	osition	outboard	centi	re thir	d row
visua	l signal				0
acoustic	signal				0
occupant de	tection		•		0
passive act	ivation	•	•		0
Head Prote	ection [evices		5.0 n	nax. 6
ļ	osition	front re	ear th	nird row	
curtai	n airbag			0	
centr	e airbag		0	0	
Chest Protection Devices 2.0 max. 3					nax. 3
	pos	ition fro	nt rea	ar	
	thorax a	irbag 💿	•)	
Neck Restr	aints			0.0 n	nax. 4
position rear outboard centre third row					
$sufficient^1$		•	•	0	
Child Read	iness			0.0 n	nax. 3
position	rear	rear	f	ront	third
	outboa	rd centre	e pas	senger	row
ISOFIX	•	•		•	0
i-Size		•		•	0
Top Tether	•	•		•	0

COMMENTS

The Aura is a 2-star performer all round, largely due the fact that ESC is not standard equipment (or even an add-on on lower variants).

primary	secondary	overall	
safety	safety	result	
30%	43%		
Evaluated variant: E 1.2 Kappa2 MT			
Evaluated on: September 9, 2025			
Protocol: FleetSure v1.0			

 $^{^{1}\}mathrm{subjective\ judgment}$