Lecture Module - Data Acquisition

ME3023 - Measurements in Mechanical Systems

Mechanical Engineering
Tennessee Technological University

Module 8 - Data Acquisition



Module 8 - Data Acquisition


- Topic 1 Analog to Digitial Conversion
- Topic 2 -
- Topic 3 -

Topic 1 - Analog to Digitial Conversion

- DAQ and Computer Storage
- Number Types
- Analog to Digital Conversion and DAQ
- Activity: ADC Resolution Calculation

DAQ and Computer Storage

A data acquisition system is the portion of a measurement system that quantifies and stores data. - Theory and Design of Mechanical Measurements



lmage: T.Hill

DAQ and Computer Storage

lumber Types nalog to Digital Conversion and DAQ ctivity: ADC Resolution Calculation

DAQ and Computer Storage

Number Types

- Integers
 - Binary
 - Decimal
 - Hexadecimal
- Fixed Point
- Floating Point

Number Types

Binary	Decimal	Hexadecimal
0	0	0
1	1	1
10	2	2
11	3	3
100	4	4
	5	5
	6	6
	7	7
	8	8
	9	9
	10	A
	11	В

Binary	Decimal	Hexadecimal
	12	С
	13	D
	14	Е
	15	F
	16	
	17	
	18	
	19	
	20	
	21	
	22	
	23	


some reference

Number Types

Binary	Decimal	Hex.
0	0	0
1	1	1
10	2	2
11	3	3
100	4	4

Binary		Decimal	Hex.
	0	0	0
	1	1	1
	10	2	2
	11	3	3
	100	4	4

Number Types



AQ and Computer Storage umber Types nalog to Digital Conversion and DAQ ctivity: ADC Resolution Calculation

Analog to Digital Conversion and DAQ

Analog to Digital Conversion and DAQ

Activity: ADC Resolution Calculation

Activity: ADC Resolution Calculation

Topic 2 -

- •
- •
- •

Topic 3 -

- •
- •
- •
- •