#### Demonstration 1 - Dimensional Instruments

ME3023 - Measurements in Mechanical Systems

Mechanical Engineering Tennessee Technological University

**Topic 2 - Using A Micrometer** 



#### **Topic 2 - Using A Micrometer**

- Overview
- Components
- Vernier Micrometer
- Digital Micrometer

### Overview


A micrometer, sometimes known as a micrometer screw gauge, is a device incorporating a calibrated screw widely used for accurate measurement of components[1] in mechanical engineering and machining as well as most mechanical trades, along with other metrological instruments such as dial, vernier, and digital calipers.

Text: Wikipedia

Unlike a pair of Vernier or digital calipers, most micrometers are designed to measure outside dimensions only.

Text: Theory and Design of Mechanical Measurements, 5th Edition

## Components



Vernier scale Thimble scale Sleeve scale

- Anvil
- Spindle
- Thimble
- Lock Ring

- Sleeve Scale
- Thimble Scale
- Vernier Scale
- Ratchet (Clutch) Knob



## Vernier Micrometer

A vernier scale is a visual aid to take an accurate measurement reading between two graduation markings on a linear scale by using mechanical interpolation; thereby increasing resolution and reducing measurement uncertainty by using Vernier acuity to reduce human estimation error. Wikipedia

<u>Pros</u>	Cons
•	•
•	•
•	•

# Digital Micrometer

A digital micrometer contains an embedded processor and user interface to facilitate the measurement process.

<u>Pros</u>	Cons
•	•
•	•
•	•