THINK HEALTHCARE AND SAFETY

MASTER INSPECTION & FITNESS CERTIFICATE

Certificate No. THS-JLL-EP9-20261030-B8A573

NOT FIT FOR USE — OUT OF SERVICE

Safety-critical defect. Remove from use until a re-test passes.

Equipment & Site

Customer / Organization	JLL	**Model**	Not recorded
Customer / Site	ETV Parcel 9 Bengaluru	**Date of Installation / Purchase**	30 Jul 2023 (est.)
City	Bengaluru	**Previous Maintenance Date**	—
Site / Location / Department	3rd Floor · Reception	**Date of Inspection**	30 Oct 2026
Equipment Type	Wheelchair	**Inspection Type**	Routine inspection
Equipment Asset ID	JLL-EP9-WC-001	**Next Due Date**	28 Jan 2027
Serial Number	Not recorded	**Technician**	Sumit Shah
Manufacturer / Brand	Med Star	**Inspection Performed By**	Sumit Shah

Inspection Summary

8	1	1	0	0	Fail
Pass	Fail	Maintenance	N/A	Rectified	Functional test

Checklist: WHEELCHAIR — EQUIPMENT-SPECIFIC CHECKLIST (template v1)

Defects & Corrective Action

#3 Wheel locks: engagement, holding function and release — Fail (safety-critical): Left wheel lock does not hold on ramp

#4 Push handles and grips — Maintenance: Grip foam worn — replace at next service

Functional / load test failed: Chair rolled with left lock engaged

Corrective action reference: CAR-EP9-0007

Declaration

This is to certify that the equipment described above was inspected on 30 Oct 2026 in accordance with the attached equipment-specific checklist and, at the time of inspection, was found NOT FIT FOR USE. This certificate is valid until 28 Jan 2027 unless the equipment is damaged, modified or fails a user check before that date.

Technician signature / date



Sumit Shah
30 Oct 2026, 05:21

Reviewer signature / date



Technical Reviewer
30 Oct 2026, 05:22

This certificate must be read together with the attached Equipment-Specific Checklist.

THINK HEALTHCARE AND SAFETY

WHEELCHAIR — EQUIPMENT-SPECIFIC CHECKLIST

Complete in addition to the Master Inspection & Fitness Certificate

Customer / Site	ETV Parcel 9 Bengaluru
Equipment Asset ID / Serial No.	JLL-EP9-WC-001
Inspection Date	30 Oct 2026
Technician	Sumit Shah
Customer / Organization	JLL
Site / Location / Department	3rd Floor · Reception
Equipment Type	☑ Wheelchair ☐ Scoop Stretcher ☐ Foldable Stretcher ☐ Stretcher
Manufacturer / Brand	Med Star
Model	
Serial Number / Asset ID	
Date of Installation / Purchase	30 Jul 2023
Previous Maintenance Date	
Date of Inspection	30 Oct 2026
Next Due Date	28 Jan 2027
Inspection Performed By	Sumit Shah

Equipment-Specific Checks

No.	Inspection / Functional Test	Status (P/F/M/NA/RECT)	Remarks / Measurements
1	Main frame, cross-bracing and seat supports	P	
2	Rear wheels, front castors, tyres and wheel attachment security	P	
3	Wheel locks: engagement, holding function and release *	F	Left wheel lock does not hold on ramp · [1 photo]
4	Push handles and grips	M	Grip foam worn — replace at next service
5	Armrests, footrests and leg supports	P	
6	Seat and backrest fabric, cushions and stitching	P	
7	Folding and unfolding operation	P	
8	Stability and manoeuvrability during normal use	P	
9	Restraints, if provided *	P	
10	Safe movement and braking during functional test *	P	

*P = Pass · F = Fail · M = Maintenance · NA = Not applicable · RECT = Rectified. * Safety-critical: a Fail places the equipment out of service until a re-test passes.*

Functional Test / Load Test Record (where applicable)


Test required by manufacturer / standard?	☑ Yes ☐ No Reference:
Test method / procedure reference	Ramp hold test with 80 kg occupant
Specified test load / criteria (if applicable)	
Actual test result / observations	Chair rolled with left lock engaged
Pass / Fail	☐ Pass ☑ Fail ☐ Not applicable

Equipment-Specific Result

☐ All equipment-specific checks passed ☑ Defect(s) identified ☑ Re-test required

Defect / corrective action reference	CAR-EP9-0007
Technician signature / date	Sumit Shah 30 Oct 2026, 05:21
Reviewer signature / date	Technical Reviewer 30 Oct 2026, 05:22

Photo Evidence



Check #3 — Wheel locks: engagement, holding function and release · 30 Oct 2026

Change History (Audit Trail)

Inspection b8a57300-2029-4892-9eed-8e3c5dcaeb9a · 23 recorded change(s)

When	By	Change
30 Oct 2026, 05:21	Sumit Shah	Inspection started
30 Oct 2026, 05:21	Sumit Shah	header.siteLocationDepartment: — → 3rd Floor · Reception
30 Oct 2026, 05:21	Sumit Shah	checks.1.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.2.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.3.status: — → F
30 Oct 2026, 05:21	Sumit Shah	checks.3.remark: — → Left wheel lock does not hold on ramp
30 Oct 2026, 05:21	Sumit Shah	checks.4.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.5.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.6.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.7.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.8.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.9.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.10.status: — → P
30 Oct 2026, 05:21	Sumit Shah	checks.3.photos: 0 → 1
30 Oct 2026, 05:21	Sumit Shah	checks.4.status: P → M
30 Oct 2026, 05:21	Sumit Shah	checks.4.remark: — → Grip foam worn — replace at next service
30 Oct 2026, 05:21	Sumit Shah	functionalTest.required: — → yes
30 Oct 2026, 05:21	Sumit Shah	functionalTest.method: — → Ramp hold test with 80 kg occupant
30 Oct 2026, 05:21	Sumit Shah	functionalTest.observations: — → Chair rolled with left lock engage
30 Oct 2026, 05:21	Sumit Shah	functionalTest.result: — → fail
30 Oct 2026, 05:21	Sumit Shah	result.correctiveActionRef: — → CAR-EP9-0007
30 Oct 2026, 05:21	Sumit Shah	Signed by technician and submitted for review
30 Oct 2026, 05:22	Technical Reviewer	Reviewed, signed and finalised (locked)