
Reaction Wheel Speed
Wheel speed (RPM)
400
300
200
100
0
-100
-200
-300
-400
0
5
10
15
20
25
30
35
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
0
-2
-4
-6
-8
-10
-12
Torque cmd
Saturated
Time (s)