

Reaction Wheel Speed
Commanded
Measured
Wheel speed (RPM)
300
200
100
0
-100
-200
0
20
40
60
80
100
120
Commanded Torque (magenta = wheel saturated)
Torque cmd
Saturated
Torque cmd (mN·m)
15
10
5
0
-5
-10
0
20
40
60
80
100
120
Time (s)