

Reaction Wheel Speed
Wheel speed (RPM)
Commanded
Measured
300
250
200
150
100
50
0
0
20
40
60
80
100
120
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
Torque cmd
Saturated
40
30
20
10
0
-10
-20
-30
-40
Time (s)