

Reaction Wheel Speed (solid = measured, dotted = commanded)
Wheel speed (RPM)
400
300
200
100
0
-100
-200
-300
-400
0
20
40
60
80
100
120
Run 051 measured
Run 051 commanded
Run 052 measured
Run 052 commanded
Commanded Torque
Torque cmd (mN·m)
600
400
200
0
-200
-400
Time (s)
Run 051 (saturated 28%)
Run 052 (saturated 49%)