
Reaction Wheel Speed
Commanded
Measured
Wheel speed (RPM)
250
200
150
100
50
0
0
5
10
15
20
25
30
35
Commanded Torque (magenta = wheel saturated)
Torque cmd
Saturated
Torque cmd (mN·m)
30
25
20
15
10
5
0
-5
0
5
10
15
20
25
30
35
Time (s)