

Reaction Wheel Speed
Wheel speed (RPM)
400
300
200
100
0
-100
-200
-300
-400
0
20
40
60
80
100
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
600
400
200
0
-200
-400
Torque cmd
Saturated
Time (s)