
Reaction Wheel Speed
Wheel speed (RPM)
350
300
250
200
150
100
50
0
0
5
10
15
20
25
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
5
0
-5
-10
-15
0
5
10
15
20
25
Time (s)
Torque cmd
Saturated