
Reaction Wheel Speed
Wheel speed (RPM)
0
-50
-100
-150
-200
-250
-300
-350
-400
0
5
10
15
20
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
400
350
300
250
200
150
100
50
0
Torque cmd
Saturated
Time (s)