
Reaction Wheel Speed
Wheel speed (RPM)
350
300
250
200
150
100
50
0
0
2
4
6
8
10
12
14
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
0
-2
-4
-6
-8
-10
-12
Torque cmd
Saturated
Time (s)