

Reaction Wheel Speed
Wheel speed (RPM)
250
200
150
100
50
0
0
20
40
60
80
100
120
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
15
10
5
0
-5
0
20
40
60
80
100
120
Time (s)
Torque cmd
Saturated