
Reaction Wheel Speed
Wheel speed (RPM)
400
350
300
250
200
150
100
50
0
0
10
20
30
40
50
60
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
0
-5
-10
-15
-20
-25
-30
Torque cmd
Saturated
Time (s)