
Reaction Wheel Speed
Wheel speed (RPM)
250
200
150
100
50
0
0
0.5
1
1.5
2
2.5
3
3.5
4
4.5
5
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
1
0.5
0
-0.5
-1
Torque cmd
Saturated
Time (s)