
Reaction Wheel Speed
Wheel speed (RPM)
250
200
150
100
50
0
-50
0
5
10
15
20
25
30
35
40
45
50
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
3
2
1
0
-1
-2
-3
-4
Torque cmd
Saturated
Time (s)