
Reaction Wheel Speed
Wheel speed (RPM)
300
200
100
0
-100
-200
0
5
10
15
20
25
30
35
40
45
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
6
5
4
3
2
1
0
Torque cmd
Saturated
Time (s)