

Reaction Wheel Speed
Wheel speed (RPM)
300
200
100
0
-100
-200
0
10
20
30
40
50
60
70
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
7
6
5
4
3
2
1
0
Time (s)
Torque cmd
Saturated