

Reaction Wheel Speed
Wheel speed (RPM)
300
200
100
0
-100
-200
-300
0
10
20
30
40
50
60
70
80
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
20
15
10
5
0
-5
-10
-15
-20
Torque cmd
Saturated
Time (s)