

Reaction Wheel Speed
Wheel speed (RPM)
Commanded
Measured
400
350
300
250
200
150
100
50
0
0
10
20
30
40
50
60
70
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
Torque cmd
Saturated
60
40
20
0
-20
-40
-60
-80
Time (s)