
Reaction Wheel Speed
Commanded
Measured
Wheel speed (RPM)
300
250
200
150
100
50
0
0
5
10
15
20
25
30
35
40
45
50
Commanded Torque (magenta = wheel saturated)
Torque cmd
Saturated
Torque cmd (mN·m)
60
40
20
0
-20
-40
-60
Time (s)