
Reaction Wheel Speed
Wheel speed (RPM)
400
300
200
100
0
-100
0
5
10
15
20
25
30
35
40
45
50
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
400
200
0
-200
-400
-600
-800
Torque cmd
Saturated
Time (s)