

Reaction Wheel Speed
Wheel speed (RPM)
400
300
200
100
0
-100
0
20
40
60
80
100
120
Commanded
Measured
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
500
0
-500
Torque cmd
Saturated
Time (s)