
Reaction Wheel Speed
Wheel speed (RPM)
100
0
-100
-200
-300
-400
Commanded
Measured
0
2
4
6
8
10
12
14
16
18
Commanded Torque (magenta = wheel saturated)
Torque cmd (mN·m)
200
150
100
50
0
Torque cmd
Saturated
Time (s)