

SAAKSHI - government-feed ANPR output report

Gujarat Police Innovation Challenge 2026 · mandatory submission item 4

Generated	2026-09-14T16:03:38.409Z
Window	2026-09-11T00:00:00Z -> 2026-09-12T00:00:00Z
Plate reads reported	4
Cameras producing reads	2
Reads with a stored crop	4 of 4
Synthetic rows excluded	11 (TRACEFIX-* demo fixtures)

What this report claims

Every row below is a plate read the analytics pipeline produced from a government sandbox feed. A read is what the OCR returned - it is not an identification of a vehicle, and on this estate most reads are not valid registrations at all. Rows from the TRACEFIX-* demonstration fixtures are excluded: they are synthetic by construction and this report covers government feeds only.

Timestamps are absolute wall-clock times derived from each frame's presentation timestamp (PTS), never from the time a frame arrived. The frame_pts_ms column in the CSV is that presentation timestamp, so the derivation is checkable rather than asserted.

Measured accuracy - and where it fails

These figures are NOT computed from this window. They come from D2-01's hand-labelled measurement of 120 vehicle instances drawn from this estate, documented with its method in docs/anpr-accuracy.md. Four reads is not a sample from which precision can honestly be computed, and a second accuracy number that disagreed with the documented one would be worse than none.

- Exact read recall (reads equal to the human label, over legible plates): 0 of 3 - 0%
- Precision (correct reads over all reads emitted): 0%
- Plate-detection recall (plate boxes over human-legible plates): 100% on n=3
- Character accuracy (1 - editDistance/len, over legible instances): 51.8%
- Human-legible plates in the hand-labelled sample: 3 of 120

Against the challenge's stated target of >90% detection/processing accuracy, exact plate reading on this estate MISSES, and it is reported as missing. The estate is dominated by wide-area CSITMS traffic-overview cameras built for traffic monitoring rather than plate capture, and the recorded window is roughly nine of twelve hours in darkness.

Limitations - cameras that produced no plate read

A camera that saw vehicles and read no plate is the normal case on this estate, and naming those cameras is more useful than a headline count. The cause is geometry and light, not a failure to run: each of these decoded frames and produced vehicle sightings.

CAMERA	NAME	SIGHTINGS	GEOMETRY
cam04	04 Paldi Circle	7633	unclassified
cam05	05 Visat teen Rasta	4589	unclassified
cam01	01 Chiman bhai Bridge	2674	unclassified

Detected plates, with timestamps and crops

CROP	CAMERA	READ	CONF	TIMESTAMP (from PTS)	PTS ms	PLATE_READ_ID
	cam05 05 Visat teen Rasta	1118R norm 1118R	0.627	2026-09-11T10:41:41.110Z	8150	66591189
	cam05 05 Visat teen Rasta	757508300 norm 757508300	0.888	2026-09-11T10:41:43.413Z	10453	751a50f5
	cam04 04 Paldi Circle	P41 norm P41	0.687	2026-09-11T10:41:51.512Z	18640	829420cc
	cam05 05 Visat teen Rasta	755508000 norm 755508000	0.575	2026-09-11T10:42:22.053Z	49093	81cef56a