KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

REPORT NO：ST-191211-1

COMPANY ：Tibbo Technology Inc.
ADDRESS ：9F-3, No.31, Lane 169, Kang-Ning St., Hsi-Chih, New Taipei City, Taiwan 22180
TEL ：886-2-26925443
FAX ：886-2-26923139
SPECIMEN ：Tibbo Project System(G2)

DATE OF RECEIVED ：2019/11/29
DATE OF TESTED ：2019/12/10

TEST / INSPECTION ITEMS：Shock Test

REMARKS：

- The laboratory is accredited by ISO/IEC 17025 General Requirements for the Competence of Calibration and Testing Laboratory.
- The results only apply to the device under test.
- This report is 6 pages, and no part of it may be abstracted or reproduced.

Test Engineer：Hsin Tai Chang	
Approval Signatory：David Lee 2019.12.19	Laboratory Head：Hsin Tai Chang

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION LABORATORY
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

TESTING EQUIPMENT：

Shock Tester ：KING DESIGN DP-1200-60, S/N：R2110086489
Controller ：DAS-105, S/N：263210255
Control Accelerometer ：B&K 4398, S/N：2209044

TEST ENVIRONMENT：

Temperature ：25℃ (25±10℃)
Relative Humidity ：60%RH (50±20% RH)

SPECIMEN：

Model ：Tibbo Project System(G2)
Quantity ：2 units

TEST SPECIFICATION：

Shock test (Operating)
Wave Form ：Half sine wave
Acceleration ：100 g
Duration Time ：6 ms
No. of Shock ：30 shocks (Each axis)
Shock Direction ：Z axis

TEST RESULT：

Describe	PASS	FAIL	Non-Judgment
Function judgment(1)	√	——	——
Appearance check	√	——	——
(1)LED display pattern, If after the test this play pattern of LEDs are unchanged then the test can be consider as “PASS”, LED display pattern of LED are different or some of the LEDs are not working, then the test might be consider as “FAIL”			

KING DESIGN INDUSTRIAL CO., LTD.
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Testing photos
Tester


KING DESIGN INDUSTRIAL CO., LTD.
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Axis Z



Axis Z



KING DESIGN INDUSTRIAL CO., LTD.
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Testing photos – Test result
Normal


KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION LABORATORY
4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Z axis

加速度 Vs 時間

訊號名稱	加速度(gn)	作動時間(ms)	速度變化率(In/s)	低通濾波(Hz)	最大加速度	最小加速度
Input1(t)	102.58	6.36	142.10	900.00	102.58	-1.51



-END-