


Monthly Report Pekerjaan TSA Preventive Maintenance Peralatan ATG Area OM, LAWE LAWE, DHP, BPP I dan UTL RU V BALIKPAPAN

19 Maret 2023

ATG PERFOMANCE




PROBLEM FOUND


LIST ITEM	STATUS
 Troubleshoot Temp tangki lawe2. New 	V
 Troubleshoot sinyal A-1 "intermitten". New 	1
 Troubleshoot sinyal amplitudo O-8. 	V
 Troubleshoot komunikasi LPG C20-01B. 	×
 Air dan Minyak V16, V17 dan V17B tampilan display di tank.net tidak menyatu (DHP). 	×
Bug Display Tanki A-16 di Tankmaster.	×
● Data sinyal A-7 tidak masuk di tankmaster. (Masih dalam pekerjaan PT. WIKA)	×

KERUSAKAN SPARE PART

LIST ITEM	STATUS
Kabel RDU ke ATG D20-07B.	Putus
Display Tankhub T-01B (DHP).	Buram
Display GWR U-11 dan U-10 (UTL).	Rusak
MST D20-17 "Menunggu Overhaul".	Rusak
• GFD A-20 dan O-23.	Rusak



Total Resetting level Monthly



Assist re-Calibration ATG

P-4, A-16, A-19, V-3, V-6, V-1, V-2, A-29, T-900, A-7

Total Verifikasi : 107
Total On Call : 4
Total Kerusakan SparePart : 0
Total Assis re-Calibration ATG : 10

PT. Control Systems

Mark rong

Mengetahui, PT. Pertamina KU V Balikpapan

- Auran