

Minggu Ke/Bulan/Tahun

: I/November/2022

Total Kerusakan Sparepart

Total Verifikasi Total Oncall

: -

Total Assist re-Callibration

On Call	Status	
* Support Callibration	turse	
x le Configurari tank A-24.	Furns!	
after Trublehoor Temp.		

	Kerusakan Sparepart	Status
1		

: 2.

Pekerjaan Lainnya	Status
	197

Assist re-Calibration ATG					Date
1) Support	Calibration	AT 6	with	DITMET	22-10-2022
					22-10-7022 27-10-7022

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

m thace

T

\_



Minggu Ke/Bulan/Tahun

: I / November / 7072

Total Kerusakan Sparepart

: 1,

Total Verifikasi Total Oncall

: 2

Total Assist re-Callibration

3

On Call	Status
Standby Switching power. SS	
the string food . >>	
Transleshoot FJB-11	

	Kerusakan Sparepart	Status	
8			

Pekerjaan Lainnya	Status	
"Change Card Temp Tank A-24" "Change Card Temp TIT"	Finish.	
	N.	

	Date			
i) Support	Calibration.	ATE WHL	DIMET	24/10/2022.
				25/10/2022
				26/10/2022
<del>2)</del> .				

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

m that

T



Minggu K	e/Bulan/Tahun
----------	---------------

: \_ / November / 8022

Total Kerusakan Sparepart

: -

Total Verifikasi Total Oncall

. .

Total Assist re-Callibration

\_

On Call	Status	Kerusakan Sparepart	Status
		1	

		Pekerjaan Lainnya	Status	Assist re-Calibra
١.	Trouble shoot	A30, parameter buil lost	Firish	
2.	Troubleshoot	E-6 Amplitudo Signal	Finish	
	AT6 Loss			
			1 11	

Assist re-Calibration ATG	Date

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

M flaccoi

T



Minggu Ke/Bulan/Tahun

: IV / November /2022

Total Kerusakan Sparepart

:

Total Verifikasi Total Oncall

: 1

Total Assist re-Callibration

	On Call	Status
Veryplean tangli	D no - 01B	Funyh

	Kerusakan Sparepart		
8			

Status
hold.
hold. Finish
hold.

Assist re-Calibration ATG	Date	
	9.	

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

M HUDOO

F.



Minggu Ke/Bulan/Tahun

: V/ November /2022

Total Verifikasi **Total Oncall** 

: 2.

Total Kerusakan Sparepart

Total Assist re-Callibration

On Call	Statu	
Assisting konusoming A.29 dungan WIKA & KPB	Funyh.	

Kerusakan Sparepart	Status	

Pekerjaan Lainnya	Status
· Verifikari ATE:	
A1, A2, A3, A5, A21, A25, A24, A27, A28	9
A4, A30, A22, A5, E1, E2, E3, E0, T30	
7202.	

Assist re-Calibration ATG	Date	

PT. Control Systems



Minggu Ke/Bulan/Tahun Total Verifikasi

: VI / November /2022

Total Oncall

Total Kerusakan Sparepart Total Assist re-Callibration

On Call	Status	Kerusakan Sparepart	Status
		X	
		*	

Pekerjaan Lainnya	Status
1. Instalan V2 dan V2	Finish
2. Veripkari ATG tank:	
000 05B, 000.05D, 000-13A, 000-13B, AH, ADO, EG, E7, O1G, DOOSA DOO-08, DOOFA, RI, RA, R7, R8, R10 DOO-08, VG, VF	d d

Assist re-Calibration ATG			Date	

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

M HAQQI



Minggu Ke/Bulan/Tahun

: VII /November / 2022

Total Kerusakan Sparepart Total Assist re-Callibration

Total Verifikasi Total Oncall

Status	Kerusakan Sparepart	Status
1 11		
1 11		
1 11		
	Status	Status Kerusakan Sparepart

Pekerjaan Lainnya	Status
1) Installari D20-11	Final.
a) Troubleshoot Dgo-OIB "Temp & FWL"	Finns
3) Verytokan - ATE tangki	
TK-101-TLC , TK-101-T1D, TK-101-T1F.	
TLA, T1B, VIB, VI7, VI7B., TK-101-TLB.	

Assist re-Calibration ATG	Date	
	Assist re-Calibration ATG	

PT. Control Systems



Minggu Ke/Bulan/Tahun

: UII/ Nounter/2022 : 18

Total Kerusakan Sparepart Total Assist re-Callibration

Total Verifikasi

Total Oncall

On Call		Status	

	Status	

Pekerjaan Lainnya	Status
1- trouble short D2012, LPG C20-01B	Finish
2. Veryskari tangki ATG	
N21020, O15, O18, D20-18, A-26, T203	
D.370-2A, D370 2B, D70-15B, C4, P-1	
D80-03, D90-040, FII, O1, P2, D-20 12	
2- Suring Alarm toungs.	Imm.

Assist re-Calibration ATG			Date

PT. Control Systems



Minggu Ke/Bulan/Tahun

: 1x/November /2022 : 18

Total Verifikasi

Total Oncall

: 3

Total Kerusakan Sparepart

Total Assist re-Callibration

On Call	Status	
Troubleshoot tangle: T202 & 0-15 Exercing level. 1080.08	Finish	

Kerusakan Sparepart	Status
× Jalus Label power 7202	
di FJB tidak ditamakan "Numpang power 3 stryal T201"	
* Menggunakan jalur ringal spare di 0-15	Funish

Pekerjaan Lainnya	Status
Varipkani tangki: A-18, A-32, A-33, 7-902, 1707  7-904, P-8, O-12, P-32, P-5, U11, U12, N1, N3,  N6, V10, V11, U10  Troublishort Tro2 & O-15	Finish

Assist re-Calibration ATG			Date	

PT. Control Systems