



Peralatan ATG Area OM, LAWE LAWE, DHP, BPP I dan UTL RU V BALIKPAPAN Monthly Report Pekerjaan TSA Preventive Maintenance

riday May 19 2023

ATG PERFOMANCE






Total Resetting level Monthly



| LIST ITEM | STATUS |
|--|--------|
| D20-07A display RDU "Dev Error" | 1 |
| Temperature Tangki A-04 Error | 1 |
| Temperature A26 selesih | 1 |
| Troubleshoot komunikasi LPG C20-01B. | 1 |
| Spot 4 Temperature D20-05A Rusak | > |
| | |
| | |
| | |
| | |
| Troubleshoot komunikasi LPG C20-01B. | × |
| Air dan Minyak V16, V17 dan V178 tampilan | > |
| display di tank.net tidak menyatu (DHP). | |
| Bug Display Tanki A-16 di Tankmaster. | × |
| Data sinyal A-7 tidak masuk di tankmaster. | × |
| (Masih dalam pekeriaan PT. WIKA) | 2 |



KERUSAKAN SPARE PART

| LIST ITEM · | STATUS |
|---|---------|
| Kabel RDU ke ATG D20-07B. | Putus |
| Display | Rusak |
| • MST D. | Rusak |
| GFD A-20 "Menunggu aman dari kemasukan air" | Rusak |
| Motherboard D20-07A | Rusak |
| Casing Head ATG D20-17 | Korosif |
| Spot 4 Temperature D20-05A Rusak | Rusak |
| | |
| | |

Assist re-Calibration ATG

P-31, P-32, R-1, D20-07A, D20-07B, D20-07C, D20-04A, D20-05C, O-15, O-16, O-17, O-6, O-8,O-1, P-01, V-07, A-31, A-32, A-02

| ta ta ta | otal Verifikasi :113 | Fotal On Call : 6 | otal Kerusakan SparePart : 1 | otal Assist re-Calibration ATG : 20 |
|----------|----------------------|-------------------|------------------------------|-------------------------------------|
|----------|----------------------|-------------------|------------------------------|-------------------------------------|

Mengetahui, PT. Pertamina RU V Balikpapan

M. HABBY

PT. Control Systems