


# Monthly Report Pekerjaan TSA Preventive Maintenance Peralatan ATG Area OM, LAWE LAWE, DHP, BPP I dan UTL RU V BALIKPAPAN

19 Januari 2023

#### **ATG PERFOMANCE**




#### **PROBLEM FOUND**

LIST ITEM	STATUS
Troubleshoot N4 FWL dan MST	×
<ul> <li>Troubleshoot komunikasi LPG C20-01B</li> </ul>	×
Troubleshoot A-20 FWL dan Temp	V
Troubleshoot E-3 FWL dan Temp	V
<ul> <li>Troubleshoot O-19 ATG Mati total</li> </ul>	1
<ul> <li>Troubleshoot P-32 FWL dan Temp</li> </ul>	1
<ul> <li>Pergantian Kabel RDU ke ATG tanki D20-07B</li> </ul>	1
Troubleshoot P-02 FWL dan MST	1
Troubleshoot R-09 FWL dan MST	1
<ul> <li>Pergantian RDU D20-05C, O-1, E-5 dan O-17</li> </ul>	¥
Intermitten V-3	1
A-20 dan E-1 FWL bug	✓
Intermitten V-17B	V.
<ul> <li>Air dan Minyak V16, V17 dan V17B tampilan</li> </ul>	×
display di tank.net tidak menyatu (DHP)	

### KERUSAKAN SPARE PART

LIST ITEM	STATUS
<ul> <li>Kabel RDU ke ATG D20-07B</li> </ul>	Putus
Display Tankhub T-01B (DHP)	Buram
Display GWR U-11 dan U-10 (UTL)	Rusak
• MST D20-17	Rusak
• GFD A-20 dan O-23	Rusak



**Total Resetting level Monthly** 



## **ATG Physical Check Resetting**

A-5, O-1, O-2, N-2, O-21, O-23, D20-13B, A-17, T-202, E-7, O-15, P-8, R-4, R-9, D20-03, O-11, O-14, R-11, O-24, P-32, O-18, O-13, T 203, P-1, D20-12, O-10, A-15, A-22, D20-04C

Total Verifikasi : 108
Total On Call : 4
Total Kerusakan SparePart : 4
Total Resetting Physical Check : 29

Mengetahui,

PT. Pertamina RU V Balikpapan

PT. Control Systems

Markey

PIDHO SEPIRI