


# Monthly Report Pekerjaan TSA Preventive Maintenance Peralatan ATG Area OM, LAWE LAWE, DHP, BPP I dan UTL RU V BALIKPAPAN

19 Desember 2022

### ATG PERFOMANCE




## **PROBLEM FOUND**


LIST ITEM	STATUS
Temp A-24 Error	· V
Parameter A-30 level hilang	4
E-6 Amplitudo sinyal hilang	W.
FWL dan Temp Tanki D20-01B hilang	1
Installasi ATG dan MST D20-11	V.
Installasi ATG dan MST V1	· · · · · ·
Display Tankhub LPG C-20-01B hilang	N.
Power T-202 tidak masuk	V
Installasi ATG dan MST V2	1
Intermitten O-15	V
Intermitten V-3	×
A-20 dan E-1 FWL bug	×
FWL E3 hilang	×
<ul> <li>Air dan Minyak V16, V17 dan V17B tampilan display di tank.net tidak menyatu (DHP)</li> </ul>	×

### KERUSAKAN SPARE PART

STATUS
Rusak
Buram
Buram
Rusak



**Total Resetting level Monthly** 



## ATG re-Calibration

E-03, E-04, A-04, A-05, A-06, A-03, A-17, A-23, E-05, A-28, A-22, A-24, A-25, A-27, A-30, E-06, O-02, O-25, R-04, T-901

Total Verifikasi : 84
Total On Call : 11
Total Kerusakan SparePart : 7
Total Assist re-Calibration : 20

PT. Control Systems

Mengetahui, PT. Pertamina RU V Balikpapan

in HADOI

T