

### PT. CONTROL SYSTEMS ARENA PARA NUSA

Beltway Office Park, B-Building 3<sup>rd</sup> Floor Jl. Ampera Raya No. 9-10 Ragunan Pasar Minggu Jakarta Selatan - 12550 Telp: 021-780.7881; Fax: 021-780.7879

# SERVICE REPORT

Tangki D2012, Spot temperature 2 dan 4 eror.

P-TSA Preventive Maintenance Peralatan ATG Area OM, Lawe-lawe, dan DHP RU V Balikpapan Selama (24 Bulan)

## SERVICE REPORT

Subject

remponatur & spot a dan 4 Error tangki Dao-12

Area

Date

. 11 Mai 2020

### A. CLAIM PROBLEMS:

temperatur 8pot 2 dan 4 Fror.

#### B. FINDING:

Penetansi spot a dan 4 nol < eort>

## C. PROBLEM ANALYSIS, ACTION TAKEN AND RECOMMENDATION:

- a) Cell resistance making making spot temperatur spot 2 dan 4 resistansi null.

  spot 1,3,5 revistansi 12 M.S. (bondsi burut.)
- tidak diperbaiti secara manual dispot masing.
- c) Masih bisa digunakan dungan menggunakan 3 spo-t uping mana porisi berada tow, mid, High level.

PT.Control Systems

MALLAND PACHEMAN

Maintenance Area 4

FORHAY.

Oil Movement