



**BUREAU
VERITAS**

REPORT OF EXAMINATION OF LIFTING APPLIANCE

REPORT No. JJ 0626-0660-5	IDENT No. BV 0704-3-2025	DATE 20.06.2026	OFFICE KINGDOM OF BAHRAIN	
Location of appliance		AT ASKAR		
Name & address of owner		SULZER, ASKAR , KINGDOM OF BAHRAIN		
Description of lifting gears		LIFTING FRAME		
State if previous reports seen and give details		JD 1225-1703-3		
State examinations and tests carried out		THOROUGH VISUAL EXAMINATION.		
Condition of Lifting Gears		SATISFACTORY		
Reference standard/work instruction		BAHRAIN MOL – MO NO. (5) ARTICLE 17; LOLER-1998		
Description Distinctive No. or Marking	SC Identification Number	DIMENSIONS	Safe Working Load	Load Test
LIFTING FRAME All steel welded construction lifting beam n=made of I-beam C/w one lifting point at top and 04 lifting points at the bottom. MES-23-768	LF 01	I-beam: 2.6 mtr (L) x 1.9 mtr (W) x 0.4mtr(H) Top lifting point: 26mm(Thickness) x 170mm (Dia) Bottom lifting point: 16mm (thickness) x 42mm (dia)	20 tonne	N.A
LIFTING PLATE All steel welded construction with single pad eye on top and 7nos of pad eyes at the bottom. MES-23-3580	LP01	Dimension: 900 mm(L) x 750 mm(W) x 20 mm(H) Top pad eye: 25mm(Thickness) x 30mm (Dia) Bottom pad eyes: 26mm (thickness) x 28mm (dia)	3000 kgs	N.A
REMARKS	-MANUFACTURER INSTRUCTION TO BE FOLLOWED -PRE-USE CHECK TO BE CONDUCTED PRIOR TO ANY OPERATION			

I certify that ...**20.06.2026**...thoroughly examined the lifting gears/tackles or appliances described and that the above is a true report of the result.

The above items should be presented for examination on or before...**19.12.2026**...

Surveyor to Bureau Veritas



HUSSAIN ALARAB

C.C Ministry of Labour

Verified By:

BEJESH BALAN

This report is delivered within the scope of the general conditions of Bureau Veritas.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by personnel of the society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.