

COCKPIT CHECKS (C/R)

EFBs/FLIGHT DOCUMENTATION.....ON BOARD
 PEDALS AND SEATS.....ADJUSTED
 SEAT BELTS/LIFE JACKETS.....FASTENED
 CIRCUIT BREAKERS.....ALL IN
 ECL's.....FLIGHT
 ROTOR BRAKE.....OFF POSITION
 OVERHEAD SWITCHES.....A/R
 STATIC SOURCES.....GUARDED
 STAND BY COMPASS.....CHECKED
 FIRE EXT. PANEL.....CHECKED
 COMPASS CONTROL.....MAG
 ENG FUEL & FUEL PUMP/XFEED.....OFF/NORMAL
 ENG MODE SWITCHES.....OFF
 MISC PANEL.....A/R
 RCP PANEL.....NORM
 DIM PANELALL MAX
 RADAR/VHF FM.....OFF
 COND & HTR/SOV.....OFF/NORM
 HYD CONTROL PANEL.....CENTERED/GUARDED
 COCKPIT & CABIN LIGHTS.....A/R
 SKYTRAC/CPI CONTROLLER.....NORM/GUARDED
 EMERG. FLOAT PANEL SWITCH.....OFF
 WIPER PANEL.....A/R
 AVCS (IF INSTALLED).....ON
 EAPS (IF INSTALLED)A/R
 LANDING GEAR HANDLE.....DOWN
 FLOAT SWITCHES (COLL).....GUARDED
 ENG GOV SWITCHES.....AUTO
 RPM SWITCH.....100% NR

BEFORE ENGINE START (C/R)

BATTERY MASTERON
 ●BATTERY MAIN & AUXON/___VOLTS
 EPU (IF USED)ON
 ●GEN 1 & 2.....ON
 ●BUS TIE.....A/R
 ●ANTI-COLL & POSITION LIGHTS.....ON
 ●MFD & CAS.....CHECKED
 ●FUEL QTY.....CROSS-CHECKED
 ●LDG GEAR/NOSE WHEEL/PARK BRK.....3 GREEN/LOCKED/ON
 POS INIT.....LOADED
 AFCSNOT ENGAGED
 EMERG LIGHTS.....ARMED
 ●FLIGHT CONTROLS.....CENTERED/FULL DOWN
 ATC CLEARANCE.....OBTAINED
 ALTIMETER SETTINGSET___ CROSSCHECKED
 POWER CHECK TARGET.....NOTED

SYSTEM CHECKS (C/R)

► FLIGHT CONTROLS.....CHECKED
 ●TEST CONTROL PANEL.....CHECKED
 EMERG FLOATS.....NO FLOAT ON CAS/CHECKED
 ●ENG BEEP TRIM.....CHECKED
 ENG GOV SWITCHES.....AUTO

FIRST ENGINE START (C/R)

MAIN BUS VOLTAGE.....ABOVE 23V
 ENGINE FUEL/FUEL PUMPON/CHECK PRESS
 ENG MODE SWITCH.....IDLE/TIMING
 GEN (BATTERY START)ON
 ENG MODE SWITCH.....FLT
 POWERPLANT.....ALL GREEN/NORMAL CAS

SECOND ENGINE START (C/R)

BUS TIE (BATTERY START)ON
 GENERATOR LOAD (BATTERY START)GREEN ARC
 ENGINE FUEL/FUEL PUMP.....ON/CHECK PRESS
 ENG MODE SWITCH.....IDLE/TIMING
 EPU (IF USED)OFF/DISCONNECTED
 GEN 1 & 2ON
 BUS TIE.....AUTO
 RADIO MASTERON
 COND & HTRA/R
 POWERPLANTALL GREEN/NORMAL CAS

FLIGHT CONFIGURATION (C/R)

MCDU PRE-FLIGHT.....COMPLETED
 DC PANNEL CONFIG (NAV/BRGs)SET/CROSS-CHECKED
 ALT SEL.....SET___FT
 DH.....CHECKED/SET 200FT
 RADAR/VHF FM.....STBY/ON
 LIGHTS (INT & EXT)A/R
 ENG MODE SWITCHESFLIGHT
 FUEL XFEED & FUEL PUMPSCHECKED/NORM/ON
 AFCSCHECKED/AP1 & AP2 ON/ATT
 INSTRUMENTS CHECK.....ALL GREEN/NORMAL CAS

TAXING (C/R)

ATC CLEARANCEOBTAINED
 NOSE WHEEL.....UNLOCKED (IF NECESSARY)
 PARK BRK.....OFF
 PEDAL BRAKES.....CHECKED
 HSI & SLIP & COMPASS.....CHECKED
 TAKE OFF BRIEFING.....PERFORMED

BEFORE TAKE OFF (C/R)

POWER CHECK.....PERFORMED
 FUEL QTY.....CROSS-CHECKED
 ENG MODE SWITCHES.....CHECK FLT
 ATC CLEARANCE.....OBTAINED
 STROBE LIGHTS/LANDING.....ON
 XPONDER & TCAS.....ON
 RADAR.....ON
 FLOATS.....A/R
 CAT AA/R
 NOSE WHEELLOCKED
 POWER PLANT.....ALL GREEN/NORMAL CAS

AFTER TAKE OFF (C/R)

LDG GEAR.....UP AND LOCKED
 RPM SWITCH (≤ 90KT)100% NR
 FD MODES.....A/R
 DH.....SET___FT
 PARK BRK.....OFF

CRUISE (C/R)

ALTIMETER SETTING.....SET
 FD MODES.....CHECKED
 RADIOS/NAV.....SET/CHECKED
 ESIS.....CROSS- CHECKE
 LANDING/STROBE LIGHTS.....A/R
 POWER PLANT.....ALL GREEN/NORMAL CAS

BEFORE DESCENT (C/R)

ALTIMETER SETTING.....SET
 ALT SEL.....SET ___ FT
 LANDING/STROBE LIGHTSON
 EGPWS/RADAR.....CONFIGURED/ON
 APPROACH BRIEFING.....PERFORMED

BEFORE LANDING (C/R)

LDG GEAR/NOSE WHEEL.....DOWN/3 GREEN/LOCKED
 PARK BRK.....A/R
 DH.....SET ___ FT
 FLOATS (AFTER SHORELINE).....OFF
 LANDING BRIEFING.....PERFORMED

FINAL APPROACH (C/R)

LDG GEAR.....DOWN/3 GREEN
 RPM SWITCH (≤ 90 KT)A/R
 AUTHORIZATION.....CLEARED

AFTER LANDING (C/R)

NOSE WHEEL/PARK BRKUNLOCKED/OFF
 RPM SWITCH100% NR
 LANDING/STROBE LIGHTSOFF
 RADAR / XPONDER.....STBY

ENGINES SHUT DOWN (C/R)

NOSE WHEEL/PARK BRK.....LOCKED/ON
 FLIGHT CONTROLSCENTERED/FULL DOWN
 BUS TIE.....ON
 ENG MODE SWITCHESIDLE/TIMING
 RADIO MASTER.....GND
 AFCS.....DISENGAGED
 VHF FM/EMERG LIGHTS/RADAR.....OFF
 COND & HTR.....OFF
 FUEL PUMPS (AFTER 1')OFF
 VENT & ENG MODE SWITCHES.....OFF
 ENG FUEL ($\leq 10\%$ NG).....OFF
 FUEL XFEEDCLOSED
 ROTOR BRAKE ($\leq 40\%$ NR)APPLY A/R

AFTER ROTOR STOPS (C/R)

INTERNAL LIGHTS..... OFF
 FUEL QTY..... NOTED
 BUS TIE / BATTERY MASTER and GEN (NG 0%).....AUTO/OFF
 BATTERY MAIN and AUX and ANTI COLL.....OFF

OFFSHORE CHECK LIST
BEFORE DESCENT (C/R)

ALTIMETER SETTING.....SET
 PARK BRKON
 ALT SEL.....SET ___ FT
 LANDING/STROBE LIGHTS.....A/R
 APPROACH BRIEFINGPERFORMED
 HELIDECK CONTACTDONE

BEFORE LANDING (C/R)

LDG GEAR/NOSE WHEEL.....DOWN/3 GREEN/LOCKED
 PARK BRK.....ON
 DH.....SET LDP
 COMPASS.....DG
 RADAR.....STBY
 FLOATSARMED
 POWERPLANT ALL GREEN/NO CAS
 LANDING BRIEFINGPERFORMED

TRAFFIC PATTERN (C/R)

LANDING SITE..... UNIT CONFIRMATION
**PF CALLS HELIDECK ICAO CODE FROM VISUAL AIDS. PM CROSS
 CHECK AGAINST FLIGHT PREVIEW AND READBACK THE NAME.**

FINAL APPROACH (C/R)

LDG GEAR.....DOWN/3 GREEN
 RPM SWITCH (≤ 90 KT)102% NR
 LANDING AREA.....IDENTIFIED & GREEN DECK
 LANDING SITE.....RECONFIRMED
PF CALLS HELIDECK ICAO CODE AND PM READBACK.

AFTER LANDING (C/R)

COLLECTIVEFULL DOWN
 RPM SWITCH.....100% NR
 FLOATS.....OFF
 ANTI COLL & EXTERNAL LIGHTS.....OFF

BEFORE TAKEOFF (C/R)

ALT SEL.....SET ___ FT
 FUEL QTYCROSS-CHECKED
 MCDU PREFLIGHT..... COMPLETED
 ENG MODE SWITCHES.....FLIGHT
 AFCS 1/2.....ON/ATT
 FLOATSARMED
 CAT A.....102% NR
 TAKE OFF BRIEFING.....PERFORMED
 ANTI COLL & EXTERNAL LIGHTS.....ON
 HLO.....THUMBS UP
 POWERPLANTALL GREEN/NORMAL CAS

AFTER TAKE OFF (C/R)

COMPASS.....MAG
 LDG GEAR.....UP
 RPM SWITCH (≤ 90 KT).....100% NR
 RADAR.....A/R
 FD MODES.....A/R
 PARK BRK.....A/R
 DH.....SET ___ FT