

COCKPIT CHECKS

EFBs/FLIGHT DOCUMENTATION.....ON BOARD
 PEDALS AND SEATS ADJUSTED
 SEAT BELTS/LIFE JACKETS FASTENED
 CIRCUIT BREAKERS ALL IN
 ECL's.....FLIGHT
 ROTOR BRAKE OFF POSITION
 OVERHEAD SWITCHES A/R
 STATIC SOURCESGUARDED
 STAND BY COMPASS CHECKED
 FIRE EXT. PANEL CHECKED
 COMPASS CONTROL MAG
 ENG FUEL & FUEL PUMP / XFEED.....OFF/ NORMAL
 ENG MODE SWITCHESOFF
 MISC PANEL A/R
 RCP PANEL NORM
 DIM PANELALL MAX
 RADAR/VHF FM..... OFF
 COND & HTR / SOV..... OFF / NORM
 HYD CONTROL PANEL CENTERED/GUARDED
 COCKPIT & CABIN LIGHTS A/R
 SKYTRAC / CPI CONTROLLERNORM / GUARDED
 EMERG. FLOAT PANEL SWITCH..... OFF
 WIPER PANEL A/R
 AVCS (IF INSTALLED)ON
 EAPS (IF INSTALLED).....A/R
 LANDING GEAR HANDLE DOWN
 FLOAT SWITCHES (COLL) GUARDED
 ENG GOV SWITCHES AUTO
 RPM SWITCH 100% NR

BEFORE ENGINE START

BATTERY MASTER ON
 ●BATTERY MAIN & AUXON/___VOLTS
 EPU (IF USED) ON
 ●GEN 1 & 2.....ON
 ●BUS TIE A/R
 ●ANTI-COLL & POSITION LIGHTS.....ON
 ●MFD & CAS.....CHECKED
 ●FUEL QTYCROSS-CHECKED
 ●LDG GEAR / NOSE WHEEL / PARK BRK3 GREEN / LOCKED / ON
 POS INIT..... LOADED
 AFCS NOT ENGAGED
 EMERG LIGHTS.....ARMED
 FLIGHT CONTROLSCENTERED / FULL DOWN
 ATC CLEARANCE.....OBTAINED
 ALTIMETER SETTINGSET___ CROSSCHECKED
 POWER CHECK TARGET.....NOTED

SYSTEM CHECKS

FLIGHT CONTROLS (1st Flight)CHECKED
 ●TEST CONTROL PANEL.....CHECKED
 EMERG FLOATSNO FLOAT ON CAS / CHECKED
 ●ENG BEEP TRIMCHECKED
 ENG GOV SWITCHES AUTO

FIRST ENGINE START

MAIN BUS VOLTAGE..... ABOVE 23V
 ENGINE FUEL / FUEL PUMPON / CHECK PRESS
 ENG MODE SWITCH.....IDLE / TIMING
 GEN (BATTERY START).....ON
 ENG MODE SWITCH.....FLT
 POWERPLANT.....ALL GREEN/NORMAL CAS

SECOND ENGINE START

BUS TIE (BATTERY START)ON
 GENERATOR LOAD (BATTERY START)GREEN ARC
 ENGINE FUEL / FUEL PUMP.....ON / CHECK PRESS
 ENG MODE SWITCH..... IDLE / TIMING
 EPU (IF USED)OFF / DISCONNECTED
 GEN 1 & 2ON
 BUS TIE.....AUTO
 RADIO MASTER ON
 COND & HTR A/R
 POWERPLANT ALL GREEN/NORMAL CAS

FLIGHT CONFIGURATION

MCDU PRE-FLIGHT.....COMPLETED
 DC PANNEL CONFIG (NAV/BRGs)SET / CROSS-CHECKED
 ALT SEL..... SET___FT
 DH.....CHECKED / SET 200FT
 RADAR / VHF FM.....STBY / ON
 LIGHTS (INT & EXT) A/R
 ENG MODE SWITCHES FLIGHT
 FUEL XFEED & FUEL PUMPSCHECKED / NORM / ON
 AFCSCHECKED / AP1 & AP2 ON / ATT
 INSTRUMENTS CHECK..... ALL GREEN / NORMAL CAS

TAXING

ATC CLEARANCEOBTAINED
 NOSE WHEEL UNLOCKED (IF NECESSARY)
 PARK BRK.....OFF
 PEDAL BRAKES.CHECKED
 HSI & SLIP & COMPASS. CHECKED
 TAKE OFF BRIEFING PERFORMED

BEFORE TAKE OFF

POWER CHECKPERFORMED
 FUEL QTY.....CROSS-CHECKED
 ENG MODE SWITCHES.....CHECK FLT
 ATC CLEARANCEOBTAINED
 STROBE LIGHTS / LANDINGON
 XPONDER & TCAS. ON
 RADAR.....ON
 FLOATS A/R
 CAT A 102% NR
 NOSE WHEEL LOCKED
 POWER PLANT.....ALL GREEN / NORMAL CAS

AFTER TAKE OFF

LDG GEARUP AND LOCKED
 RPM SWITCH (≤ 90KT) 100% NR
 FD MODES.....A/R
 DH.....SET___FT
 PARK BRK.....OFF

CRUISE

ALTIMETER SETTING.....SET
 FD MODES.....CHECKED
 RADIOS / NAV.....SET / CHECKED
 ESIS.....CROSS- CHECKED
 LANDING / STROBE LIGHTSA/R
 POWER PLANT..... ALL GREEN / NORMAL CAS

BEFORE DESCENT

ALTIMETER SETTING.....SET
 ALT SEL..... SET ___ FT
 LANDING / STROBE LIGHTSON
 EGPWS / RADAR.....CONFIGURED / ON
 APPROACH BRIEFING..... PERFORMED

BEFORE LANDING

LDG GEAR / NOSE WHEELDOWN / 3 GREEN/LOCKED
 PARK BRK A/R
 DH..... SET LDP
 FLOATS (AFTER SHORELINE)..... OFF
 LANDING BRIEFING.....PERFORMED

FINAL APPROACH

RPM SWITCH (≤ 90KT) A/R

FINAL APPROACH RECHECK (MEMORY ITEMS) PERFORMED

AFTER LANDING

NOSE WHEEL / PARK BRKUNLOCKED / OFF
 RPM SWITCH 100% NR
 LANDING / STROBE LIGHTSOFF
 RADAR / XPONDER.....STBY

ENGINES SHUT DOWN

NOSE WHEEL / PARK BRK.....LOCKED / ON
 FLIGHT CONTROLSCENTERED / FULL DOWN
 BUS TIE.....ON
 ENG MODE SWITCHESIDLE / TIMING
 RADIO MASTERGND
 AFCSDISENGAGED
 VHF FM / EMERG LIGHTS / RADAR.....OFF
COND & HTR OFF
FUEL PUMPS (AFTER 1') OFF
 VENT & ENG MODE SWITCHES..... OFF
 ENG FUEL (≤ 10%NG)..... OFF
 FUEL XFEEDCLOSED
 ROTOR BRAKE (≤ 40%NR)APPLY A/R

AFTER ROTOR STOPS

INTERNAL LIGHTS..... OFF
 FUEL QTY..... NOTED
 BUS TIE / BATTERY MASTER and GEN (NG 0%).....AUTO / OFF
 BATTERY MAIN and AUX and ANTI COLL..... OFF

OFFSHORE CHECK LIST
BEFORE DESCENT

ALTIMETER SETTING.....SET
 PARK BRKON
 ALT SEL..... SET ___ FT
 LANDING / STROBE LIGHTS A/R
 APPROACH BRIEFINGPERFORMED
 HELIDECK CONTACTDONE

BEFORE LANDING

LDG GEAR / NOSE WHEELDOWN / 3 GREEN / LOCKED
 PARK BRK.....CHECK ON
 LANDING SITE**GREEN DECK**
 DH..... SET LDP
 COMPASSDG
 RADAR STBY
 FLOATSARMED
 POWERPLANT ALL GREEN/NO CAS
 LANDING BRIEFINGPERFORMED

TRAFFIC PATTERN

LANDING SITE..... UNIT CONFIRMATION
**PF CALLS UNIT NAME READ FROM VISUAL AIDS. PM CROSS
 CHECK AGAINST FLIGHT PREVIEW AND READ BACK THE NAME.**

FINAL APPROACH

RPM SWITCH (≤ 90KT) 102% NR

FINAL APPROACH RECHECK (MEMORY ITEMS)PERFORMED

AFTER LANDING

COLLECTIVE FULL DOWN
 RPM SWITCH.....100% NR
 FLOATS.....OFF
 ANTI COLL & EXTERNAL LIGHTS.....OFF

BEFORE TAKEOFF

ALT SEL.....SET ___ FT
 FUEL QTYCROSS-CHECKED
 MCDU PREFLIGHT..... COMPLETED
 ENG MODE SWITCHES..... FLIGHT
 AFCS 1/2.....ON / ATT
 FLOATSARMED
 CAT A..... 102% NR
 TAKE OFF BRIEFING..... PERFORMED
 ANTI COLL & EXTERNAL LIGHTS.....ON
 HLO.....THUMBS UP
 POWERPLANTALL GREEN/NORMAL CAS

AFTER TAKE OFF

COMPASSMAG
 LDG GEAR.....UP
 RPM SWITCH (≤ 90KT)100% NR
 RADAR A/R
 FD MODES A/R
 PARK BRK.....A/R
 DH.....SET ___ FT