

<u>Summary information for PrismaPro-Users regarding firmware updates:</u>



Main issues:

Table 1: Firmware 1.5.0 → 1.6.0

#	Арр	Issue	Description of change
01	API	Dig. Output	Updated default digital output channel modes to be OFF
02	API	Status of Filament	Added API targets to access the status of filaments 1 and 2. API-Nbr: 63 /mmsp/status/fil1Open/ and API-Nbr: 64 /mmsp/status/fil2Open/
03	API	Ext. pressure gauge	"External Pressure gauge" is now working
04	API	OEM ID	oeMID = 33
05	API	Login	Username: OEM 33 PWD: see PV-Cloud "EULA-Users" for correct Login



Table 2: Firmware 1.6.0 → 1.9.0

#	Арр	Issue	Description of change
01	WebUI	External Pressure	Shows ext. Pressure gauge
02	WebUI	Total Pressure	Shows total Pressure in different units
03	WebUI	Tune	Tune folder added
04	API	Login	Removed OEM restrictions: Non-Eula-Users don't need login Can do MID-Scan and Lock/Release PrismaPro without "login"
05	WebUI	Monitor	mBar has been added as a unit for measuring Total Pressure and External Gauge Pressure.
06	WebUI	Monitor	Calculation of pressure data has been corrected so that the number displayed is now accurate Previously some unit conversions were being miscalculated.
07	WebUI	Monitor	Scan EM Voltage can now be changed from the Monitor screen. - The input is validated by confirming that the new voltage is within the device's accepted bounds.
08	WebUI	Monitor	Plot Y-Axis scaling has been modified to allow downscaling to accomadate dramatic decrease in data magnitude, such as when EM is turned off.
09	WebUI	Tune	The default scan mass now tries to select the first mass after 1, if possible. - This is done to try to prevent users from attempting to tune mass 1.
10	WebUI	Tune	Adjusting scan parameters (dwell, ppamu, etc.) will now behave properly such that the changes do not take effect until the user clicks 'SET'.
11	API	ControlLock	WriteMode changed from 'protected' to 'normal'.
12	API	Documentation	Some api targets have had their descriptions updated to more accurately describe the intended use.
13	WebUI	Tune	Removed Cal Gas button from tune page to prevent confusion
14	API	Service only	Added Support for Right Angle electronics
15	API	Documentation/Firmware	Modified return value of Digital Input HW Values from U16 to U32 so it could fit all channels
16	API	Documentation	Fixed Analog/Digital IO Layout Tables for PrismaPro API Doc to match the IO Layout of PrismaPro
17	API	Documentation	Changed some endpoint descriptions to more accurately describe intended use



Table 3: Firmware 1.9.0 → 1.9.1

#	Арр	Issue	Description of change
01	FW	Firmware Right Angle RGA	Adjust RF sweep frequencies for 90 degree PrismaPro
02	API	rfBoardRightAngle	Added query only API command to see if a 90 degree PrismaPro unit