



# PrismaPro via API

(see also Flowchart\_ControlPrismaPro):

## e.g. PVMassSpec is open:




If Scan-Monitor is running, PVMassSpec has full control and locked the PrismaPro:



We can use this API to know if PrismaPro is locked and ask the clientName and can send an error-code to the PLC!

After PVMassSpec has stopped the "Acquisition" or the PCMassSpec is closed, everybody can take the control:



Now we can take the control via API:

# 1. Set Clientname


http://172.16.14.42/mmsp/communication/clientName/set?PfeifferVacuum

#### 2. Set Control

http://172.16.14.42/mmsp/communication/control/set?force


#### 3. Set ControlLock

http://172.16.14.42/mmsp/communication/controlLock/set?Session




The PrismasPro is locked now for other applications!

If PVMassSpec try to start the Acquisition, this Error will appear:



After 6 minutes without any request the control will change back to "everybody":



If we don't need the PrismaPro, we can switch back the API's "control " to "release" and the API "controlLocked" to "Unlocked", so PVMassSpec or anybody else can take the control again, if necessary.

Release the control via API:

#### 1. Set ControlLock

http://172.16.14.42/mmsp/communication/controlLock/set?Unlocked

### 2. Set Control

http://172.16.14.42/mmsp/communication/control/set?release