





# PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 4/1/032 N30Y

PROPELLER MODEL AND SERIAL HC-H3 WF-1RF/F7693DF LX459B

HUB SERIAL A-90975B BLADE SERIALS K70120 , K70114 , K7012)

D5519-2-13

#1



DATE 2008	TOTAL IN SER		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE	
19	HOURS	10ths		& NUMBER	
4/7/08	٥	0	engine S/N 802969, aircraft 411032	engine S/N 802969, aircraft 411032	
,			at Hobbs time <u>ク. ク</u> .	mie	
				Mike Hardet	
a deservice deservices	4			OUARE 100129CE	
10/19	32	3	PRESSED SMALL NICK IN PROPELLERTIP. RETURNED TO SENVICE,	2614 19204 A 48	
2009	84.	7	PERFORMED 50-H, 100-H, ANNUM INSPECTION. I CERTIFY THAT THIS PRIFECTION TO SERVICE INSTALLED ON N344 CESSNA LG41-1550FG SN-411032	2400133 IA	
	Magazagan pendebang Managan sa Asa				

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED					AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER		
19	HOURS	10ths								
Jan 26 2011	TACH 143.	7	PROPELLER Hartzell HC-H3YF1RF  Complied with the FAA Airw Performed applicable Inspe Manual Chapter 5-20-00.  1. Lubricated propeller hub I certify that this PROPELLI Inspections and compliance.	ction Operation  ER has been i	ective Bi-Week ns in accordan	ce with the (	Dessna LC41- h the <b>50/100-</b>	cH date Ja 550FG M	Maintenance	it
41/6			returned to service.  NAME & SIGNATURE  ENRICO M. REYES	E CE	RTIFICATE 0133 IA	·	ATE	WOF	S121007	
	,									







DATE	TOTAL TIME IN SERVICE HOURS 10ths		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE	
				& NUMBER	
agenta <sup>27</sup>			LOG CLOSED - SEE LOG 2		
		3. West and Adv.			
gi consil					
			•		



A Textron Company

### PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION  $\frac{41032}{N30Y}$ PROPELLER MODEL AND SERIAL  $\frac{HC-H3YF-IRF}{F7693DF}$ LX459B

HUB SERIAL \_\_\_\_\_BLADE SERIALS <u>K70120</u>, <u>K70114</u>, <u>K70121</u>

D5519-2-13

#3







DATE	Cessna		Sortel Aircraft st Experienced Cessna Corvalis Se 817.468.7788 Fax: 817.468.5611		SNATURE, TYPE ER
	400MM04. INSTALLED N	-	REE PROP BLADES. AD'S CHECKED THRONCE WITH A 100 HOUR INSPECTION AND	CESSNA 400 MAINTENANCE MANUAL OUGH BIWEEKLY 2015-16. WAS DETERMINED TO BE IN AIRWORTHY	

DATE	DATE TOTAL TIME IN SERVICE		PROP MODEL: HC-H3YF-1RF	Turbine Aircraft Services, LLC.	DATE: 8/12/2015 A/C TSN: 368,3	SIGNATURE, TE TYPE
19	HOURS	10ths	PROP S/N: LX459B REG: NO: N3UY WORK ORDER: 11029	Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone: 405-491-8995	PROP TT 368.3 HOBBS: 368.3	IBER
		0	Prop Entries			
			(4) Completed a 100 hour F guide to inspect this Propel	Propeller inspection, utilizing Cessna 400 model LC41-550FG Ma ler.	aintenance Manual Chapter 5 inspection	
			The Aircraft and/or component(s found Airworthy for return to serv	) items identified above were repaired and inspected in accordance with curice. "Pertinent details of this repair are on file at this repair station No. TBW	rrent Federal Aviation Regulations and was R469X". N3UY 11029 8/12/2015	
			DATE: 8/12/2015	SIGNED South	Work Order: 11029	
				James C. Morphew Certified Repair Station No. TBWR488X	Printed by EBis 3 (datcomedia.com)	-
,						
			ga garretti i kondiza garriti serilitik i interationi olasi seriliti.			
			er alla di Mangadi espapore estra matala alla alla di Arabania esta e esta en			
	a			1 of 1		





DATE	TE TOTAL TIME IN SERVICE		PROP MODEL: HC-H3YF-1RF	Turbine Aircraft Services, LLC.	DATE: 9/2/2016 A/C TSN: 512.2	IGNATURE
19	HOURS	10ths	PROP S/N: LX459B REG. NO. N3UY WORK ORDER: 11333	Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone: 405-491-8995	PROP TT: 512.2 HOBBS: 512.2	BER
			<b>Prop Entries</b>			
			(3) Completed a 100 ho inspection guide to inspe (51) Dressed out prop b		00FG Maintenance Manual Chapter 5	
			Airworthy for return to service	ent(s) on N3UY was repaired and/or inspected in accordance with current ewith regard to work performed on this work order. "Pertinent details of Order No. 11333 Dated 9/2/2016  SIGNED:		
				James Morphew	Printed by EBis 3 (datcomedia.com)	
				Certifled Repair Station No. TBWR469X		
			i kanangan i manimpanta. Per negari di Sebura Menimpanta kanan Mengelebekan pertekan kengalah pepil b	Color (a. a. Color de		

DATE	TOTAL TIME IN SERVICE		PROP MODEL: HC-H3YF-1RF	Turbine Aircraft Services, LLC.	DATE	11 January, 2018 A/C TSN 616 6	SIGNATURE, TE TYPE
19	HOURS	10ths	PROP S/N: LX459B  REG NO N3UY  WORK ORDER: 11766	Repair Station No. TBWR469X 7101 Millionaire Drive, Hangar 21 Bethany, Oklahoma 73008 Phone, 405-491-8995		PROP TT 616 6 HOBBS 616 6	BER
			Prop Entries				
			(3) Completed a 100 hour Prinspection guide to inspect the (31) Blended propeller blade		C41-550FG Maintenance Manual Cha	pter 5	
			Airworthy for return to service with	on N3UY was repaired and/or inspected in accordance with regard to work performed on this work order. "Pertinent deter No. 11766 Dated 11 January, 2018	tails of the inspection/repair are on file at thi		
				James C. Morphew Certified Repair Station No. TBWR469K	Printed by EBis 3 (d	latcomedia.com)	
#*************************************				en e	populari en en espera por transferanti de di escone escone de primi e e transferanti.		. ,
				1 of 1			