


SSP-1872-1



LYCOMING

652 Oliver Street Williamsport, PA. 17701 U.S.A. Form No. 2481 (3/04-LM)

This engine has been rebuilt in accordance with the applicable Lycoming specifications. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are new or newly rebuilt. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model: IO-540-K1G5D Serial #:

0.0

RL-27438-48A

Total Time:

Work Order #: AD244897

Date Completed: 1/15/05

Authorized Signature

Lycoming Engines

Lina

652 Oliver Street Williamsport, PA. 17701 Production Certificate #3


Date: 3/8/2005, Aircraft: N848T, Type: PA32R301, S/N: 32R-13027, Tach: 2026.2, Total Time: 2026.2 Installed factory rebuilt engine, Lycoming IO-540-K1G5D s/n RL-27468-48A, Lycoming WO# AD244897. Installed new Lord mounts, p/n J9613-12/19, and new engine mount bolts, p/n AN7-35A. Installed propeller, m/n HC-C3YR-1RF s/n DY2224, and propeller governor, m/n F-4-11B s/n D2587UJ, after overhaul by H&H Propeller Service, Inc., WO# 13829. Installed new breather tube, p/n 38166-000, and new breather hose, p/n MIL-H-6000-1". Installed all new hose assemblies, drain hoses, and SCAT duct firewall forward. Installed new hose and Adel type clamps firewall forward. Installed overhauled alternator, p/n ALY-6521-R s/n E121927, Kelly Aerospace WO# M722370. Installed new alternator belt, p/n 37A19773-367. Installed new fitting, p/n AN816-4-4, and new wiring to hourmeter oil pressure switch. Installed new engine air filter element, p/n BA3. Cleaned, inspected, repaired, and painted engine baffling. Installed new baffle seal, p/n T-8071. Fabricated and installed patch over cracked area of muffler heat shroud. Installed new Knisley Welding exhaust risers, p/n K38137-02/03/04/05/06/07, and new Aerospace Welding, Inc. mufflers, p/n PMA67517-00. Installed overhauled vacuum pump, p/n 211CC s/n 9553, Holly Aero WO# 9553. Installed new vacuum hose, p/n MIL-H-6000-5/8 from vacuum pump to firewall fitting. Installed two new central air filters, p/n D9-18-1, and vacuum regulator filter, p/n B3-5-1.

ense

mber

WO# 14844 Triad Aviation, Inc.

FAA CRS# PP4R448M (800)334-6437 Michael L. Branham, DOM



EN	GI	N	E	L	0	G
the s was	W II	H . M	Daniel .	Cheese.	~	-

Date	Ti	me			Signature	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - RE	MARKS	Signature	Number
5-25-05			DAMEDOIL SUSPECT FILTE	F / SCHENS NO FAULT	sNotel sav	ICE WHH
TACH	2103	1	119ts AERO 15/50. Suspect A	A. Filder. Service	- Plugs Int	PECTMAS
H6BB5	264	2	Time. INSpect General Conc	VILLIAMS, CLAKS, CLA	CKS Etc. INSP	Ect Prop Go
		<	EMPERT FOR NEW RECUITING F	105/3Bs. Compt	ESSIONS ASA	ollow:
			075 6 70 3 78 9 75 6 276	075 RUNUP LEA	K CHECK, OF	SCHECK
			Satistactory	The property of	//	
		<	Spenti by that this ENGINE	HAS BEEN SUSPEC	etel in Accom	LANCE
with	A	60	41 Suspection And WAS D	Etermine to E	E ; N AirWo	1440
C	md	tion	J. Date 3-05-05	FRANTENTICOS	46BBs 26	4.2
			1000 Bande	AP 247A1955		
			Page Total	All Repair Data Must Bear	the Endorsement of a	
			Brought Forward Total to Date	Certificated Mechanic, and Certificate Number MUST b		

Date	Ti	me			Signature	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	Number
Holles	2150. 312	,3	Daired Engine oil removed, cut open, in old oil filter - no engine particles to compare installed new CH 40103-1 of and safetial, Souved engine with 1 approached 15/50 oil DA A - 1 DA	spected spected il filten		
			The Digerth 14.	710-71		land Land
			Page Total Brought Forward Total to Date All Repair Data Certificated Medicate Num	chanic, and h		

ENGINI	FIOG	
PIAGIIA	LLUG	

Data	Ti	me			E. H. Dewit	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMA	RKS	Signature	Number
8-26-05			Dogmad Engine oil removed	cat open.	9/37	d Rossill
tach	2199	8	inspected oil filter - no) engine		4 - 4.
Hobbs	036	3.4	particles found - install.	I new	Para HASK	
			CH48103-1 oil filter !	exvired		
	riche d	1 1	engine with light. Acrosh	11 6/00	16 A A A A A A A A A A A A A A A A A A A	4 705
	ACT C	04.03	chare oil. Saffied new i	il filter.	artiment Palist	
400	100	0	PAS S	1 8 232577		M aves
	Marie C		ware y			17/1
		-	V 10195 255	(3)-13-1178E		
			Page Total Al	Repair Data Must Rear t	he Endorsement of a	
		bri	Brought Forward Ce	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
			Total to Date			

Date	Ti	me		
	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature License Number
8-26-05			C/W AD 2002-26-01/MSB 3425	, Fuel injectore lines, pue 2299.
fach	2199	8		, rei, garactes, pae our co
Hosbs	036	3.4	Jo Sig	LP2725379
5-7-05			Drained engine oil removed oil filt	R cat spon and property -
tach	227	1.4	engine particles Count - institut and	
Hob4.	6439	112	oil fifter geowited enine with 1	ate Acrosted to low evine
			oil. Head Did P2105	379
			Page Total	
			Certificated I	ta Must Bear the Endorsement of a Mechanic, and his Rating and
	200		Total to Date Certificate N	ımber MUST be Shown.

ENGINE LOG	Serial No.
	Serial No.

Date	Time Hrs Min		REPAIRS - ADJUSTMENTS - SER	VICE - REMARKS	Signature	License Number			
-14-05			Removed cowling d.	and entre of benevi	2				
L 720	8.8			inspected no contour					
0/94 0	163.6	2	Cound lastalled wen	CH48 103-1 al					
			Elter Sufetial, Service	red enginewith					
			(gto Leroskell W100 pearse oil						
			Yw. AD2002-26-0	1 AD 95-26-13					
			next due 239878 for b	oth. Teto M.D.	18277	379			
		-	Page Total	All Repair Data Must Bear	the Endorsement of a	والإنجاد			
			Brought Forward Total to Date	Certificated Mechanic, and Certificate Number MUST	I his Rating and				

			ElaQuar F	34	Seliai No.		
Data	Time				Signature	License	
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - R	REMARKS		Numbe	
		: 09 Feb	ad consisted with 11 OTS of Aeroshell W-100. Re	emoved	573 o 13 2 18 CH A		
oil filt and s gapp cylind STD Perfo	er and safetied ed, all siders. Find 1925. Cormed Cornel C	checked compres	Indicate the work of the control of	e e e e e e e e e e e e e e e e e e e			
- Davi	4180	hwartz (cPL# 2854977 D. Pasek A&P 250650417				
			Page Total	All Repair Data Must Bear the Endorsement of a			
			Brought Forward	Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.			
			Total to Date				

Des D. S.	01	BA # 5	, m	0	0
EN		Ni		·	1

Serial No. ___

	STREAMENTE	Signature	License Number
N848T Date: 06 March 2006 Tachometer: 2501.3 Hobbs: 669.2			
Drained engine oil and removed oil filter. Old filter can was opened and			
inspected for debris, none was found. Serviced engine with 11qts. of		200	D. David St.
Aeroshell W-100. Installed new CH48103-1 Champion oil filter and	DOMESTIC STREET		
safetied. Engine ran and leak checked, OK.	STREET, STREET	in without or the	
Checked the following recurring AD's on this airframe:		Mark Inches	
AD2002-26-01:Fuel injector lines checked visually, due at Tach	LEED PLYSLY	90-271-0-11	
2601.3			M Unit
 AD2005-12-06: D6LN-3000 Magneto is installed, has "A" in lower Right 			
quarter of data plate, thus per AD it is snap ring equipped. This AD			
due at Tach 2526.2.			
 AD95-26-13: oil cooler hoses checked visually next due at Tach: 			
2601.3			
Aircraft returned to service.			
Flort A. L.			
Peter M Giegerich A&P 2725379			
- 100 m - 100	Repair Data Must Bear	the Endorsement of	
	ficated Mechanic, and		
	ficate Number MUST I		

			ENGINE LOG Ser	ial No.	
Date	Time		DEDAUGE AD HIGHMENTS CERVICE DEMARKS	Signature	License Number
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		- A
1-10-06	723	4	DraineDoilED & KEPLACE OIL TILTER.	Wes 130	2551
			SONVICE WITH 11sts 15/50 AEROSHELL.	1911/211/10	
			LEAK OHECK SATISTACTORY.		
			N848T Date: 10 May 2006 Tachometer: 2603.6 Hobbs: 771.6		
			Checked the following recurring AD's on this airframe: AD2002-26-01:Fuel injector lines checked visually, due at Tach 2703.6 AD95-26-13: oil cooler hoses checked visually next due at Tach: 2703.6.		
			Aircraft returned to service. Jon D Pasek, AP 250650417	idorsement of ating and	a

100 No. 100 No

			ENGINE L	OG	Serial No.	
Date	Ti	me			Cianatura	License
	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - I	REMARKS	Signature	Number
6-2-06	Pr.		Drink Poil ! Juspect	SCHOOL / FILTER.	SINSTALL NEW) filter
TACH DG	34,0	10	And Service with 119ts	AETO 15/50.	Service Pluce	AND TEST.
Hobbs 8	29.	5	KEPLACE I YLUG. REPLE	REALTHIGER.	RETIME MAD	
		(LASPECT for New/ Pecon	ing ADS/SBS	Complessio	25.0
D 75	0	746	375 @ 75 @ 76 @ 76	Suspect Con	odtion-LEA	K, Clacks, El
KUNC	P/1	EA	K CHECK SAtistactory			0
Sto	Hi	ty	THAT THIS ENGINE, HA	S DEEN SUSPEC	CTED in ACCO	relance
with	AF	ANK	UAL GOODS LNSACTION	AND WAS VETER	mINE to BEIN	A. ruboth
Cond	Hiz	w.	Date 6-2-06	1		
			alsia	was JAD	17869551	
			Page Total	All Repair Data Must Be	ar the Endorsement of a	
			Brought Forward Total to Date	Certificated Mechanic, a Certificate Number MUS	nd his Rating and T be Shown.	

A	ving National Aviation 2 uthority/Country: A/United States	AUTHORIZED RI				3. Form Tr QAA#	24759		
. Organi	zation Name and Address:	Quality Aircraft Accessories Inc. (QYI 5746 E. Apache, Bldg. A Tulsa, OK 74115		877-833-694 918-835-694 918-835-280	8	5. Work Ord INV #	er/Invoice Number: 4469/	nature	License Numbe
. Item	7. Description	8. Part/Number	9. Eligibility*	10. Qty	11. Serial/Batcl	h Number	12. Status/Work		I W
1	MAGNETO	10-682560-13	(VARIOUS)	1	A0989	05GR	OVERHAUL		
See Atta	ached Work Order Summary	OHR. M PULSE N for details. (2) pages we were manufactured in conformity to:			1		(MECH: KR)		
See Atta	ached Work Order Summary fles the items identified abo	for details. (2) pages we were manufactured in conformity to:	19. 214 CFR of Certifies Block 12	13.9 Return to that unless of and describe	Service Oth	ner regulatio In Block 13, accomplishe	(MECH: KR) on specified in Block 13 the work identified in id in accordance with		
See Atta	ached Work Order Summary fles the items identified abo App wed design data and ar	for details. (2) pages we were manufactured in conformity to:	19. 14 CFR 4 Certifies Block 12 Title 14, C	13.9 Return to that unless of and describe cose of Feder b) is (are) app	Service Oth	ner regulation in Block 13, accomplishert 43 and in 1 service.	(MECH: KR) on specified in Block 13 the work identified in d in accordance with respect to that work, val/Certificate No.:		
See Atta	ached Work Order Summary fies the items identified abo App. wod design data and ar Non-approver design data si	for details. () pages we were manufactured in conformity to- se in a condition for safe open non secified in Block 13	19. Certifies to Block 12 Title 14, C the Itempo	13.9 Return to that unless of and describe code of Feder of (are) app Signature:	o Service Otherwise specified in Block 13 was a land a Regulations, par roved for return to	ner regulation in Block 13, accomplishert 43 and in a service. 21. Appro	(MECH: KR) on specified in Block 13 the work identified in d in accordance with respect to that work, val/Certificate No.: QYIR334Y		

Pallereninger out to short gas as a lie n. noticoming noticities in baues in other of the principle of the p UNOI 39 REU HELDIE 34 3089 Socool Sonstrament herolis sees on the nimber of the state of the state of the sees of the state of the sees of the state of the state of the sees · I. You'd ut balloads Things and of Whorking sessitiffown in the to not believe of the following sessitiff the sessitification the sessitiff the sessitiff the sessitiff the sessitification the sessitiff the sessitification the sessitiff the sessitification the sessitificati Then has an of who that seeming which he is not seeming the seeming the seeming of the seeming the see of Whorks almistoo Wishbrows for 2806 gross mennood sith to sortesting and the service of the representation o MAMOSSE AUGUSTUS DE REPRESENTANTE DE LE PROPERTIE DE LE PROPER 6.06/8 mio 4 AA4 Tachometer: 2727 Hobbs: 896.1 N848T Date: 18 July 2006 Serial No. Drained engine oil and removed oil filter. Old filter can was opened and inspected for debris, none was found. Serviced engine with 11qts. of License Aeroshell W-100. Installed new CH48103-1 Champion oil filter and KS Signature Number safetied. Checked mag timing, cleaned and gapped plugs and rotated top to bottom, performed compression check: all cylinders 79/80 psi. Engine ran and leak checked, OK. Checked the following recurring AD's on this airframe: AD2002-26-01: Fuel injector lines checked visually, due at Tach 2827 AD95-26-13: oil cooler hoses checked visually next due at Tach: 2827 Aircraft returned to service. Tachometer: 2727 Hobbs: 896.1 N848T Date: 27 July 2006 Complied with AD 2005-12-06 "TCM magneto inspection on Lycoming 450 Peter M Giegerich A&P 2725379 series engines" Magneto (m/n D6LN-3000, p/n 10-682560-13) failed due to stop pin wear and broken distributor gear teeth on both the right and left magneto. Installed Overhauled D6LN-3000 magneto form Quality Aircraft Accessories, p/n 19-682560-13 s/n A098905GR FAA Form 8130-3 t/n QAA# 34759. Removed old condensers from magneto ignition harness cap and installed two new condensers p/n 10-382681. Operational check satifactory. Aircraft returned to Page Tota AD 2005-12-06 next due @ 3227 Tach Brought F nent of a nd

Total to D

Peter M Giegerich, A&P 2725379

EN	GI	N	E	L	0	G
No. 10 AM	-		STATE OF THE PERSON.	- BREEZ	~	-

Date	Ti	me	DEDAUGO AD HIGTMENTO OF	DVICE DEMARKS	Signature	License Number
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SE	RVICE - REMARKS		Number
15/06	94	1.6	Hobbs RAINED ENGI	WE OIL, REMOVED O	12 FILTER, C	UT OPE
1	27	75.7	Tuch AND INSPEC	TOO FOR CONTAMIN	ANTS, NOVE	Forms
			INSTALLED A	18W CH48103-1 OIL	FILTE AND	SAFEII
			SERVICED	ENDENE WITH 119to	AGROSHELL	W100
	Him		EXPLINE, OF	L. LEAK CHECK GO	on AIRCR	APT
			RETURNED	TO SERVICE .	& Mouse	1 AEF
						1
					27	25379
			Page Total	All Repair Data Must Bear t	he Endorsement of a	
	Alls		Brought Forward	Certificated Mechanic, and	his Rating and	
			Total to Date	Certificate Number MUST b	e Shown.	

			ENGINE LOG Serie	al No.	
Date	Ti	me	TO THE PERSON OF	Signature	License Number
Date	Hrs Min R	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		, tuilles	
			Drained engine oil and removed oil filter. Old filter can was opened and inspected for debris, none was found. Serviced engine with 11qts. of Aeroshell W-100. Installed new CH48103-1 Champion oil filter and safetied. Checked mag timing, cleaned and gapped plugs and rotated top to bottom, performed compression check: all cylinders 79/80 psi. Engine ran and leak checked, OK. Checked the following recurring AD's on this airframe: AD2002-26-01:Fuel injector lines checked visually, due at Tach 2934.8 AD95-26-13: oil cooler hoses checked visually next due at Tach: 2934.8. Aircraft returned to service.		
			Jon Pasek A&P 250650417 Jon D Certificate Number MUST be	indorsement of lating and Shown.	a

EN	GI	N	F	1	0	G
-14	VII.	11.	lian.	-	U	U

Date	Tir Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE - RE	EMARKS TELEVISION OF THE PROPERTY OF THE PROPE	Signature	License Number
0.4-06	988H	4	ADJUST OIL PRESSURE.	Partorn, Run Factory.	4824796	7357
9:31'04	295	3.7 4.9	Perform FIEWALL FWD: REPLACE SPACK PLUGS. Perform Comp. CHECK O 475 675 @76	Expection. CHECK MAG TIME 73 070 375		
1 (1) (1)		960 (d	Page Tatal			
		176	Page Total Brought Forward	All Repair Data Must Bear t Certificated Mechanic, and I	nis Rating and	
			Total to Date	Certificate Number MUST b	e Shown.	

			ENGINE LOC	s s	erial No.	
Date	Ti	me	THE STATE OF THE PERSON OF THE	ADVC	Signature	License Number
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMA	ARKS	1000	Number
N	1848T	Date: 2	21 October 2006 Tachometer: 2940.3 Hobbs: 110	7.9	EGAL BIR	
ir ir	nspected	for deb	il and removed oil filter. Old filter can was opened and oris, none was found. Serviced engine with 11qts. of Installed new CH48103-1 Champion oil filter and and gapped plugs and rotated top to bottom 02-26-01:Fuel injector lines checked visually, due at To	Part of	1-28 17.2253 1-3250 17.451 1-34-301	Done.
-	Aircraft r	eturned	to service.	250	Part (A)	
	Joshua	Burrow :	2749851 Johnson A+	P		
				All Repair Data Must Bea		
				ertificated Mechanic, an ertificate Number MUST		

Total to Date

ENGINE LOG	EN	GIN	EL	OG
-------------------	----	-----	----	----

Date	Ti Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	License Number
Dec 15,7	006	116	C/W AD2002-26-01 by visu	al inspac		injection
Hobbs	1(8	ul	2 3114,5 tach Acrosaft ref	wared b	ext inspect service.	on our
Remo	R-301 ved en specte hell W	gine co d filter	20, 2007 Tach: 3104.7 Hobbs: 1276 Wiling for oil change. Drained oil and removed filter. Cut open no significant metal found. Serviced engine with 11qts. gine oil and installed new Champion CH48103-1 oil filter and cleaned and tested engine bearing the control of the control			
3&4 p	lugs wi	th new ervice.	cleaned and tested spark plugs. Replaced top 1&2 and all Champion RHM38E plugs. Leak check satisfactory. Aircraft)ata Must Bear Mechanic, and Number MUST b	the Endorsement of a his Rating and be Shown.	

1

Carial Na

1			ENGINE L	.0G S	erial No.	
Date	Tin	ne			Signature	License
Date	Hrs Min		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	Number
			Engine Entry N848T 20 February 2007 Tach: 3126 Lycoming O-540	.9 Hobbs: 1299.2	o Pales	(res
			Drained engine oil and removed oil filter. Ometal particles found. Serviced engine with one CH48103-1 oil filter. AD2002-26-01:F at Tach 3226.9. Leak check satisfactory. AP Peter M Giegerich, A&P 2725379	h 11qts. Aeroshell W100 engine ruel injector lines checked visually	oil and	
23-07	TAC	EN 31	27.1 REPLACED RT M	MAGNETZ CABACI	ton P/N 16-40	0570
				2 fail 561920	478AB	
			Page Total Brought Forward	All Repair Data Must Bear Certificated Mechanic, and		
			Total to Date	Certificate Number MUST		

Date	Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE	- REMARKS	Signature	License Numbe
8-07	TAC	H:	3134.4 INSPENGING	= IAN AN AMUA	LINSP.	N ES
	T.T.	11	08.2 CHANGED OI	L AND FILTER.	CLEAN INSO	2
133	0	7		PARK PLUCS. REPO		
			HOSES W/ RE	UD. LEAK CK A	ND RUN UP	OK
	9"	STATE OF THE PARTY.	COMPRESSION	I Certify That This	CINE Has Been	
	-	4 1	2 3 4 5 6	Inspected In Accordance W	ith An HANNE	
	1	8180	(5180 74 80 71 80 77 80 75 80	Inspection And Was De	termined To Be In	1
				Airworthy Condition. Ti		
*	TE I			1108.3 Date	3-8-07	./
11	-		Page Total	Signed All Repair Data Must Bear t		4187
			Brought Forward	Certificated Mechanic, and	his Rating and	
			Total to Date	Certificate Number MUST b	e Shown.	

Date Ti Hrs 3-22-07 3	Min REPAIRS - ADJUSTMENTS - S REPAIRS - ADJUSTMENTS - S	NETO TO REPL	Signature	License Number
3-12-07 3	169 9 RTR MAG	NETO TO REPL		
	CAPACMUR.	2 1	ACE LEFT	170=
	911.1011	C/W AD 05-1 x=.045 THE	2-06	
	X=.042/	x=.045 TU	= AGAIN IN 500	HKS
	1	Pr. A		
	561	520478AP	Total District	
	See a face of the Recognition of the Local and popular			
	The tenumum and the set of the set		WILL KILL STEEL STEEL	4006
	tight see at east the fight of Authority	12		
				H
	Page Total	All Repair Data Must	Bear the Endorsement of a	
	Brought Forward	Certificated Mechanic Certificate Number M		

EN	GI	N	F	1	0	G
F 1 A	u	111/4	No.		$oldsymbol{\circ}$	u

Date	Time Hrs Min	REPAIRS - ADJUSTMENTS	- SERVICE - REMARKS	Signature	License Number
30-07	TACH 31	76.8 CHANGED	OIL AND FILTER.	Land Market	1 14/4
		SERVICE	6/ 11/575 AS 100 W.	N Trails JIT	N L
		LEAK CH	W/ 11/675 AS 100 W.	3-410-1-	
			0 //	1.01	
		11			
		5619		THE COL	
7400			DE 22 1 1 1 1 1 1 1 1 1	EL HS	
		All most	Enter South Town Joseph	A AMELIER OF	
DAY.		1500 100	LANCE VICENA DE	tomer the	
15 110		25.51 11.52	PATENT SCHOOLS	A PART OF THE	
		Page Total	All Repair Data Must Bea	r the Endorsement of a	
		Brought Forward	Certificated Mechanic, an	nd his Rating and	
		Total to Date	Certificate Number MUST	be Shown.	

/		ENGINE LO	OG Ser	ial No.	
Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - R	EMARKS	Signature	License Number
4/04/07		Changed oil & filter	Serviced	2. Ex. 10 - 11-30 c	Ja-al
FACH	3176.8	W/ 111 Qts A5/100W	+ CH48103	26.00	
-		Oil Filter. Leak ch	eck ok.	ELECTION S	250
		Gal thinking 24.8987	1329 AN		
5/11/07		Changed oil Efiller 5	ierviced w/		
TACH	3225.3	11 Qts AS/100W + CH42	8103-1 Oil filter		
		leak check O.K. I'm A	1002-26-01 by	isual	
		inspection of lines + clar	ps Performed	Compression	chee
		#1 75 #270 #373 #4 Page Total Oal halve?	74, #5 74, #6 75	. Cleaned sp.	wk Plu
		Brought Forward 1179731947	All Repair Data Must Bear the Certificated Mechanic, and his	Endorsement of a	
		Total to Date	Certificate Number MUST be	Shown.	

Date	Ti	me				License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARK	(S MB AT HE LATE A	Signature	Number
6-14-07			MANGED OU AND FIL	TEN	exwal-usion	No.
TACH	327	7.0	STAVICED W/ 11 GTS ASIUD			
			LEOK CK OK			
			101			
		+1	CHEROLOGICAN.	out de la		EVIL
7110			361 1 204 17110	USTERTU	728ct 33 72	179.23
1-27-07			WONT IN CHEST	F ET AB., T		
TACH :	332	0.1	CHANGED OIL AND FILTER, I	CLEAN INSI	AND REGAT	
				SK		
			1/n.h.	561920178x	30	
			Page Total All R Brought Forward Certif	epair Data Must Bear t	he Endorsement of a	
				ficated Mechanic, and ficate Number MUST b	nis Hating and e Shown.	

/		ENGINE L	OG Se	erial No.	
Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE -	REMARKS	Signature	License
9-18-07	TARA:	3367.4. CHANGED BIL 1	MAND FILTER. SE	suct w/ 11	0/5
		ASIDOW.	at ge ox	12 (T. D. S. Ext.)	T W
		5619	20478188		-
25.07	TACK:	JIMED TO ENCIN	REPLACED MX	GNETS W/	OIK
	73.531	TIMED TO ENCIN	E DPS CK	GOLD	150-
		56192	247818	Mark III are	Irla
		Page Total	All Repair Data Must Bear t	he Endorsement of a	
		Brought Forward Total to Date	Certificated Mechanic, and I Certificate Number MUST be	his Rating and	

	0	BA S	_		-	1
		I I N B	Diam.		a B	-
EN		111 76		-	w	U

Serial No. ___

Data	Tir	me				License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE -	REMARKS	Signature	Number
17-08	TAC	M:	3465.8 CHANGED 01	L AND FILTER	CONTROL FOR S	1134
			SERVICE W	11 QTS AS 100W	PANTERS ST	
1050	18	490	LEAK CK O.	Mary May 12 mg	1 1889 Hank	
7572	B), y	1 10	10.	L		
			56/7	70478AP		
	ouve	anH.	SHOOS AND AND YOURS AT THE			
		TWEE	May a Was a South of Act and a South of Act		I R DE LE	
Barrell	nt u8	oT by	America and the Americanian - 1-	all offers of the second		
	1 10	alviel	all partitions of white Partitions of the Partition of th			
ow the day.			7-90			
Seattle a sea	-		Page Total	All Repair Data Must Bear t	he Endorsement of a	
			Brought Forward	Certificated Mechanic, and I	nis Rating and	
			Total to Date	Certificate Number MUST be	e Shown.	

Doto	D-4-	Tin	ne				Lice	
900	Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVIC	E - REMARKS	Signature	Nui	
the item identified above	-08	TAC	4:	3511.4 INSPENG TI	AN AN ANNUAL INSI	Not don	180	
ntifi		T.7	:	1485.7- CHANZED OU	PARO THITER SPRING!	111855		
n ide		TSM	140	1485.2 AS 100 W. REPL	ACED STANTER WINE	W comor o	miz	
iten	V.			REPLACED FW	MUFFLER WINEW	KNISLEY PINK	1675	
s the				LEAK CK AND RUE		, , , , , , , , , , , , , , , , , , , ,		
Certifies 1				WWW.		Certify That This.	ENCINE Has Bee	n
		1	2	COMPRESSION 5 6	Inspected In Accordance			
		74/80	73 8	76 80 76 80 77 80 75 80	Inspection And Was	Determined To Be	n	
			E		Airworthy Condition	Time In Service:	1-7	
					1485,2	ate 4-4-08	-	
7 27				Page Total	All Repair Data Must Bear t	he Endorsement of a	20%	
2		7		Brought Forward	Certificated Mechanic, and Certificate Number MUST b	his Rating and		
				Total to Date	Certificate Number 191031 b	e Snown.		

CANAL CO.

Date	Ti	me			11.19.11.11.71.11	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	Number	
5-5-08	7	ACH	3549,5 Retorney all	Ite conveite Plate	Studto 60	Flas
			Read lip al felter torqued it	Ite conveite Plate		
			RITE	ill .		
			1/307085	7)4		
					167-1 7 16	
			22 C W W W W W W W W W W W W W W W W W W			
					THE RELEASE	
			Page Total	All Repair Data Must Bear th	o Endorsement -f -	
		100	Brought Forward	Certificated Mechanic, and h	is Rating and	
			Total to Date	Certificate Number MUST be Shown.		

	Ti	me		OFFINIOR DEMARKS	Signature	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS		A SECTION ASSESSMENT	
7-08	TA	TAL:	3549.7 REPLA	CED OIL FILTER ADI	APTEN DUE	- 1838
			TO LEK	OK, CHANGED OIL AND	DFILTER	
1 1			SERVIC	CH OK 11 DIS ASIL	rw.	Market 1
	MA	3 5	LEAK	CH OK	en caratral 78	78 8 75 7
7-11				10 1		
	T P	W	EN FIRE FEE TO	I and	de l'ALACENE (
				561926470AP		
					The Page of Shirt I had a	
					hen Tues Superior	
		e 6		CHAPTER HERE		
	1		Page Total	All Repair Data Must	Bear the Endorsement of	of a
			Brought Forward	Certificated Mechanic Certificate Number M	, and his Rating and	
			Total to Date	Certificate Number W	OG F De Onown.	

ENGINE LOG Serial No. Time Date FAARepair Station No. PP4R448M FOR: ACCOMPLISHED BY Hrs Min SERIAL NO. MODEL Signed REMARKS: PART NO. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER REPAIR. THE AIRCRAFT ENGINE OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE. MANUFACTURER LYCONING Order No. TRIAD AVIATION, INC. 3439 South Aviation Drive Burlington, NC 27215 Signature of Authorized Representative 0-540-KIGED 17356 SERVICEABLE PARTS muce M 19047 CM 6-16-08 TACH: Date_W

			ENGI	NE LOG	Serial No.	
Date	Tir Hrs	me	REPAIRS - ADJUSTMENTS - SE	RVICE - REMARKS	Signature	License Number
6-6-08	71	ACN	3666.7. CHANGE	INSP PAR REC	TEN	
1242			CLEAN	INSP PND REC	of Span Placs	
			56,	192017840		
6-16-08	TAC	4:	3611.3 REPLACE	D #6 C42 W/	OlN ON LW 190	47 CA
-			RULUP OI	11	AND COLUMN AND SECTION OF THE PARTY OF THE P	
			2	Du. L 5619	2047848	
			Page Total Brought Forward	All Repair Data Mus	st Bear the Endorsement of a	
			Total to Date	Certificated Mechan Certificate Number	nic, and his Rating and MUST be Shown.	

Total to Date

ENGINE LOG Serial No. Time License Date Signature REPAIRS - ADJUSTMENTS - SERVICE - REMARKS Number Hrs Min 9-26-08 3700.2 COMPRESSION 3 4 76 80 1/80 75 80 75 80 76 80 77 80 girle Page Total All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. **Brought Forward** Total to Date

	DATE	Instructions & A D Notes
cense umber	5-25-65 HOBBS	264.2 TACH 2103.1 C/W AD 2002-26-01 FUEL GINE TWSD. NEXT DUE
T NAME		ACH 2203.1. Yors Bough A+PO47969551
100	5-25-05 HOBBS 20	WID TACK 2103.1 C/W AD 95-26-13 OIL HOSE JOHD. NEXT DUED
	HOBBS 364.25	
	5-25-05 HOBBS 2	64.2 TACH 2103.1 O/W AD95-26-13 OIL HOSE REPLACE NEXT DUEB
0	HoBBs 1187.3 T	ACH 3026.2 yes Bargh A+P 247865351
V - \	5-25-05 HoBBs	264.2 TACH 2103.1 CLW AD96-12-7 impulse coup NEXTDUER
	HoBBS 687.3	
	ABBS 478.25	INCH 2313.2 C/W ADOS-19-11 /5B5660 N/A BY 5/W
No.	Ches Bang	- A+P247869551
	HobBs 478.2"	TICH 2313.2 CIW 5B 548A NIA BY DATE CODE
	Chola Bana	L ATP 247969531
	HOBBS 478.2 TH	el 2313.2 ADOS-12-06 DUE @ TACH 2526.2

AJJADANGLE AT 24716755) 65342 FIEL INTINES 6-3-06 HOBBS 802.3 NEXT DIE @ 902.3 UNES BANG AT 247869551 AD 95-2613 OIL COOLET LINES 6-3-06 HOBBS 802.3 NEXT DIE @ 9 UNES BANGE AT 24819551	
UNES BOURT AP 2479(ASSI AD 95-26-13 OIL COOLER LINES (52-06 HOBBS 802:3 NEXT DUE Q 9 GUES BOURT AP 2479(ASSI AD 02-26-01 FIRE LINE JAJ. 6-2-06 HOBBS 802:3 NEXT DUE Q 90	202.3 Hai
UNES BOUND AND 2479 (ASS) AD 95-26-13 OIL COOLER LINES (52-06 HOBBS 802.3 NEXT DUE Q 9) UNES BOUND AND 24 POUR AND SSI AD 02-26-01 FUEL LINE JUD. 6-2-06 HOBBS 802.3 NEXT DUE Q 90.	. 00
4002-26-01 Fige Line JAJ 6-2-06 HOBBS 809.3 NEXT DEQ 90	Hobbs
4002-26-01 Fige Line JAJ 6-2-06 HOBBS 809.3 NEXT DEQ 90	07348
	CZ-STOL
	2.3 481
	h echiah
	Land
	Land Street