
HW3 report

FSM:



Screenshot:

```
Pattern 40 is passed !
Pattern 41 is passed !
Pattern 42 is passed !
Pattern 42 is passed !
Pattern 43 is passed !
Pattern 44 is passed !
Pattern 44 is passed !
Pattern 45 is passed !
Pattern 46 is passed !
Pattern 46 is passed !
Pattern 47 is passed !
Pattern 48 is passed !
Pattern 48 is passed !
Pattern 50 is passed !
Pattern 50 is passed !
Pattern 50 is passed !
Pattern 51 is passed !
Pattern 52 is passed !
Pattern 53 is passed !
Pattern 54 is passed !
Pattern 55 is passed !
Pattern 56 is passed !
Pattern 57 is passed !
Pattern 58 is passed !
Pattern 60 is passed !
Pattern 61 is passed !
Pattern 62 is passed !
Pattern 63 is passed !
Pattern 64 is passed !
Pattern 65 is passed !
Pattern 66 is passed !
Pattern 67 is passed !
Pattern 68 is passed !
Pattern 69 is passed !
Pattern 60 is passed !
Pattern 60 is passed !
Pattern 61 is passed !
Pattern 62 is passed !
Pattern 63 is passed !
Pattern 64 is passed !
Pattern 65 is passed !
Pattern 66 is passed !
Pattern 67 is passed !
Pattern 68 is passed !
Pattern 98 is passed !
Pattern 99 is passed !
Pattern 99 is passed !
Pattern 90 is passed !
```