Tim Hollaberryh Engineering Clinic	(13	
Part 1 1. Define significant Cigures		
Nomber of digits reported for the valves of a	a measured	
or calculated quantity		
Z. How i's a number's number of significent figures	different from	
its number of decimal places?		
The significant figures can include numbers + of the decimal point. For example, 405.5 has	soue deimn?	
pluces, but y significant liquos.		
7. Rula In Zeva		
tous are significant when		
1. They are between of her significant file Z. Zeros to vight of your beg but after declinal	ant in t	
Zerus ave not significant when		
1. Preceding a definal point with no number Z. Precede first non-zero digitand	is tethe left	
4. Rules for multiplication and division Result should have no more significant finns	as their the	
Extruit The Lewest significant digits		
5. Rules for addition and subtraction		
Give some nom bor of deimal places as then		
the Easter with the land number of decimal,	places	
6. Ruk for exact numbers Do not factor into significant figure cala		
Do not fector into significant figures cold	uler for us	