Two estimates were obtained for fixing up the old church building.

The first estimate was that it would be cheaper to build a new structure than to fix the current. There are major problems with the foundation that will be difficult to fix. These problems will continue to compromise the structural integrity of the building. Some of the walls are already bowing and there are large cracks. This will only get worse with time.

An estimate was obtained from a different contractor for "cosmetic" fixes that did not deal with the foundation problems. This includes:

- Trimming back the tree branches hanging over the roof
- Repairing and painting the roof
- Installing gutters
- · Minor repairs and painting of the outside
- Minor repairs and painting of the inside walls and ceiling
- Minor repairs and painting of the floor

The estimate for the above work is \$15,000.