




1. Assumes a 12V DC motor, which applies zero volts with respect to ground to both VMOTOR1/2 when not moving, +12V to one and 0V to the other when moving in one direction and the reverse when moving in the other.
2. Trigger outputs provide a pair of "dry contacts" isolated from the other circuitry. Connect them according to the needs of the gate controller, e.g. one to ground and one to its trigger input.
3. OPENED and CLOSED are connected to any relevant (active-low) limit sensor(s). (The Shelly Plus I4 provides internal 10K pullup resistors to +V.)
4. The SW input on the Shelly Plus 1 is unused. It may be useful for a PE safety sensor.

GateKeeper v4.6
25/5/2026