
PLAN VIEW





INTERNATIONAL EROSION CONTROL SYSTEMS INC.


22295 Hoskins Line Rodney, ON, NOL 2C0 Phone: 800-821-7462 Fax:866-496-1990

www.iecs.com


CABLE CONCRETE - WEIR CONECTION DETAIL

DRAWN BY:	R	J	CHEC	KED BY:	L. A
SCALE: N.T.S	DATE: 08/21/15		SHFFT 1	OF 3	

DETAIL A - ONE BLOCK KEY IN



DETAIL B - MAT-WEIR CONNECTION





INTERNATIONAL EROSION CONTROL SYSTEMS INC.

22295 Hoskins Line Rodney, ON, N0L 2C0 Phone: 800-821-7462 Fax:866-496-1990


www.iecs.com

CABLE CONCRETE - WEIR CONECTION DETAIL

DRAWN BY:	R. s	J	CHEC	KED BY:	L. A
SCALE: N.T.S	DATE:	08/21/15		SHEET 1	OF 3


MAT CONNECTION

PROFILE VIEW




WHEN PLACING THE MATS, THE GAP BETWEEN THE MATS SHOULD NOT BE ANY LARGER THAN A 50mm (2") MAXIMUM. IF THE MATS ARE PLACED WITH A LARGER SPACE THAN 50mm (2"), IT IS RECOMMENDED TO GROUT THE SEAM BETWEEN THE MATS.

CABLE CLAMP



NOTE: CABLE CLAMPS ARE MADE OF A U-BOLT, A COVER SADDLE, AND TWO NUTS.

PLAN VIEW



POSITION CABLE CLAMP AS SNUG TO THE BASE OF THE CONCRETE BLOCK BY SLIDING CABLE CLAMP DOWN TO THE ADJACENT LOOPS, THEN TIGHTEN CLAMP SECURELY.



INTERNATIONAL EROSION CONTROL SYSTEMS INC.

22295 Hoskins Line Rodney, ON, NOL 2C0

Phone: 800-821-7462 Fax:866-496-1990

www.iecs.com

CABLE CONCRETE - WEIR CONECTION DETAIL

DRAWN BY: R. J CHECKED BY: L. A

SCALE: N.T.S | DATE: 08/21/15 | SHEET 3 OF 3